

District I
1625 N French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax (575) 393-0120

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING LLC		API Number 30-025-21364
Property Name VACUUM GLORIETA WEST UNIT		Well No 013

1. Surface Location									
UL - Lot C	Section 25	Township 17S	Range 34E		Feet from 660	N/S Line FNL	Feet From 2310	E/W Line FWL	County LEA

Well Status								
TA'D WELL YES	NO	SHUT-IN YES	NO	INJ NO	SWD NO	OIL PRODUCER OIL	GAS NO	DATE 7-23-2024

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	20	20
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if
					applicable

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Waiting on Rig

Signature 		OIL CONSERVATION DIVISION	
Printed name Jesus Romero		Entered into RBDMS	
Title Field Specialist		Re-test	
E-mail Address Romero@fieldops.com			
Date 7-23-2024	Phone 682-352-4714		
Witness			

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 388462

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 388462
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/10/2024