

Oil and Gas
 1000 E. 10th Ave. Box 1000
 Denver, CO 80202

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Benton Crude Oil LLC	API No. 30-025-28013
Property Name Humphrey Queen	Well No. 031


1. Surface Location									
Lot A	Section 3	Township 25 S	Range 37 E	Feet from 1300	N/S Line S	Feet from 1750	E/W Line W	County Lea	

TUBEWELL		SHUT-IN		INJECTOR		PRODUCER		DATE	
YES	NO	YES	NO	YES	NO	YES	NO	9-18-24	

OBSERVED DATA

	(A) Surface	(B) Intermt(1)	(C) Intermt(2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	VAC
Flow Characteristics					
Puff	Y	N	Y	N	CO2
Steady Flow	Y	N	Y	N	WTE ✓
Surges	Y	N	Y	N	GAS
Down to nothing	Y	N	Y	N	Type of fluid Exposed for Waterhead if applies
Gas or Oil	Y	N	Y	N	
Water	Y	N	Y	N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding (test down or continuous build) up if applies

Signature	OIL CONSERVATION DIVISION Entered into RBDMS Re-test 
Printed name	
Title	
E-mail Address	
Date	
Phone	
Witness	Gary Robins

INSTRUCTIONS ON BACK OF WELL FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 386005

CONDITIONS

Operator: Benton Crude Oil LLC 2201 Menaul Blvd NE Ste A Albuquerque, NM 87107	OGRID: 331974
	Action Number: 386005
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/10/2024