

District 1
1625 N French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax, (575) 393-0120

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING LLC		API Number 30-025-30126	
Property Name VACUUM GLORIETA WEST UNIT		Well No. 102	

1. Surface Location									
UL - Lot P	Section 36	Township 17S	Range 34E	Feet from 990	NS Line FSL	Feet From 990	E/W Line FEL	County LEA	

Well Status									
TA'D WELL YES	NO	YES	SHUT-IN NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 6-13-2024	

OBSERVED DATA

	(A)Surface	(B)Intern(1)	(C)Intern(2)	(D)Prod Csg	(E)Tubing
Pressure	8	N/A	N/A	60	180
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 WTR _____ GAS _____ Type of Fluid Injected for Waterflood if applies
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature 		OIL CONSERVATION DIVISION	
Printed name Jesus Romero		Entered into RBDMS	
Title Prod. Geol.		Re-test	
E-mail Address Jesus@OCDNM.org			
Date 6-13-2024	Phone 682-362-4714		
Witness			

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 388502

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 388502
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/10/2024