

District 1
1625 N French Dr, Hobbs, NM 88240
Phone (575) 393-6161 Fax: (575) 393-0120

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING LLC		API Number 30-025-41356
Property Name CENTRAL VACUUM UNIT		Well No 211

Surface Location									
UL - Lot L	Section 6	Township 18S	Range 35E		Feet from 1930	N/S Line FSL	Feet From 645	E/W Line FWL	County LEA

Well Status									
TA'D WELL YES	NO	SHUT-IN YES	NO	INJ NO	INJECTOR NO	SWD NO	OIL YES	PRODUCER NO	GAS NO
									DATE 8/3/24

OBSERVED DATA

	(A) Surface	(B) Intern(1)	(C) Intern(2)	(D) Prod Csg	(E) Tubing
Pressure	0	0		50	100
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 WTR _____ GAS _____ Type of Field Inferred for Waterflood if applies
Steady Flow	Y/N	Y/N	Y/N	Y/N	
Surges	Y/N	Y/N	Y/N	Y/N	
Down to nothing	Y/N	Y/N	Y/N	Y/N	
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Well is down; waiting to be pulled

Signature <i>Richard Paul</i>	OIL CONSERVATION DIVISION Entered into RBDMS Re-test
Printed name Richard Paul	
Title Lease Operator	
E-mail Address paul@ctfieldsvcs.com	
Date 8/3/24	
Phone (817) 739-5643	
Witness	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 385451

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 385451
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/10/2024