



OIL CONSERVATION DIVISION  
 ACTEC DISTRICT OFFICE  
 1000 RIO BRAZOS ROAD  
 ACTEC NM 87410  
 (505) 334-5178 FAX (505) 334-5179  
 HDB - 6000 State St. US 666 District 10

# BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11/26/24 Operator Wapiti API #30-0 07-20194  
 Property Name VPR A Well No. 44 Location: Unit 0 Section 32 Township 32 Range 20  
 Well Status (Shut-In or Producing) Initial PSI: Tubing 90 Intermediate NA Casing 14 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
5 min	0	1	14		
10 min	0	1	14		
15 min	0	1	14		
20 min					
25 min					
30 min					

## FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Nothing upon opening Bradenhead Valve - Nothing after 5 min

By Danille S. O'Donnell  
operator

Witness \_\_\_\_\_

(Position)

Stamp Address

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 405789

CONDITIONS

Operator: Wapiti Operating, LLC 1251 Lumpkin Rd Houston, TX 77043	OGRID: 328741
	Action Number: 405789
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	None	12/11/2024