Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161 Energy	y, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283		WELL API NO. 30-015-29777
811 S. First St., Artesia, NM 88210 OIL C	CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	220 South St. Francis Dr.	STATE FEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND R	EPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRIL	L OR TO DEEPEN OR PLUG BACK TO A	OXY PEARL STATE
DIFFERENT RESERVOIR. USE "APPLICATION FOR P. PROPOSALS.)	ERMIT" (FORM C-101) FOR SUCH	
1. Type of Well: Oil Well Gas Well	Other	8. Well Number #001
2. Name of Operator		9. OGRID Number
OXY USA WTP LP		192463
3. Address of Operator	9	10. Pool name or Wildcat
PO BOX 4294, HOUSTON, TX 77210	U	PARKWAY; MORROW, WEST (GAS)
4. Well Location Unit Letter   1980   fe	from the SOUTH 15 and 66	O fort from the EAST line
	eet from the SOUTH line and 66 line and 50	
Section	Ownship 198 Range 29E on (Show whether DR, RKB, RT, GR, etc.	TVIVII IVI
11. Elevati	on (Show whether DK, KKB, K1, GK, etc.	.)
12. Check Appropriate	Box to Indicate Nature of Notice.	Report or Other Data
12. Check rippropriate	Box to maleute tratale of fronce,	report of other Butu
NOTICE OF INTENTION		SSEQUENT REPORT OF:
	ABANDON 🔲 REMEDIAL WOF	
TEMPORARILY ABANDON   CHANGE F		RILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE	COMPL CASING/CEMEN	IT JOB
DOWNHOLE COMMINGLE		
CLOSED-LOOP SYSTEM  OTHER:	□ OTHER:	
	ons. (Clearly state all pertinent details, ar	nd give pertinent dates, including estimated date
13. Describe proposed or completed operation		nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU		
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.	JLE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA	JLE 19.15.7.14 NMAC. For Multiple Co	
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.	JLE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA	JLE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA	JLE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA	JLE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA	JLE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA	JLE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA	JLE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA	JLE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA	JLE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA CAPPED ON 11/4/2024.	JLE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA	JLE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA CAPPED ON 11/4/2024.	JLE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA CAPPED ON 11/4/2024.  Spud Date:	TLE 19.15.7.14 NMAC. For Multiple Co.  JOB NOTES ARE ATTACHED  Rig Release Date:	ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA CAPPED ON 11/4/2024.	TLE 19.15.7.14 NMAC. For Multiple Co.  JOB NOTES ARE ATTACHED  Rig Release Date:	ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA CAPPED ON 11/4/2024.  Spud Date:	TLE 19.15.7.14 NMAC. For Multiple Co.  JOB NOTES ARE ATTACHED  Rig Release Date:	ompletions: Attach wellbore diagram of
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA CAPPED ON 11/4/2024.  Spud Date:	TLE 19.15.7.14 NMAC. For Multiple Co.  JOB NOTES ARE ATTACHED  Rig Release Date:	ompletions: Attach wellbore diagram of THE WELLHEAD WAS CUT AND  ge and belief.
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA CAPPED ON 11/4/2024.  Spud Date:  I hereby certify that the information above is true.	Rig Release Date:  and complete to the best of my knowledge TITLE REGULATORY ENGIN	THE WELLHEAD WAS CUT AND  ge and belief.  DATE 12/10/2024
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA CAPPED ON 11/4/2024.  Spud Date:  I hereby certify that the information above is true.  SIGNATURE SIGNATURE STEPHEN JANACEK	Rig Release Date:  and complete to the best of my knowledge TITLE REGULATORY ENGIN	ompletions: Attach wellbore diagram of THE WELLHEAD WAS CUT AND  ge and belief.
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA CAPPED ON 11/4/2024.  Spud Date:  I hereby certify that the information above is true.	Rig Release Date:  and complete to the best of my knowledge TITLE REGULATORY ENGIN	THE WELLHEAD WAS CUT AND  ge and belief.  DATE 12/10/2024
13. Describe proposed or completed operation of starting any proposed work). SEE RU proposed completion or recompletion.  THE FINAL WELLBORE AND PA CAPPED ON 11/4/2024.  Spud Date:  I hereby certify that the information above is true.  SIGNATURE STEPHEN JANACEK	Rig Release Date:  and complete to the best of my knowledge TITLE REGULATORY ENGIN	THE WELLHEAD WAS CUT AND  ge and belief.  DATE 12/10/2024

Well Name: OXY PEARL STATE #1
API 14: 30-015-29777-0000
PE: STEPHEN JANACEK
Date: 12/10/2024

## Surface Casing:

Hole Size: 17 1/2"
Casing Size: 13 3/8" @400'

Casing Weight: 48#

Cement Details: 620 sxs to 0'

Circ 12 sxs @ surf

## Intermediate Casing:

Hole Size: 11"

Casing Size: 8 5/8" @3,240'
Casing Weight: 24-32#
Cement Details: 1400 sxs to 0'

Circ 323 sxs @ surf

# **Production Casing:**

Hole Size: 7 7/8"

Casing Size: 4 1/2" @11,550'

Casing Weight: 11.6#

Cement Details: 525 sxs to 9,082' (CBL)


Did not Circ @ surf

# Tubing:

Tubing Size: 2 3/8"
Tubing Depth: 10,780'
Packer Depth: 10,780'

Perforations 10,826' - 10,840' 11,262' - 11,268' 11,349' - 11,355' CIBP @11,415' 11,423' - 11,427' 11,441' - 11,444'

11,451' - 11,454'



# OXY PEARL STATE #001 30-015-29777 PA JOB NOTES

Start Date	Remarks
	CREW TRAVEL TO LOCATION
	HPJSM W/ ALL PERSONAL ON LOCATION
	PERFORMED PRE-TRIP RIG INSPECTION
	LOAD EQUIPMENT DROVE PULLING UNIT & REVERSE UNIT PUMP ASSOCIATED
10/8/2024	EQUIPMENT FROM THE PURE GOLD B FEDERAL 011 TO THE OXY PEARL STATE 001
	HPJSM W/ ALL PERSONAL ON LOCATION DISCUSSED FIT FOR DUTY, STAY HYDRATED
	DRINK WATER TAKE BREAKS EAT FRUIT, ZERO TOLERANCE, HAND & FINGER SAFETY
	CAMPAIGN, STOP WORK AUTHORITY, LOTO, PPE, MEET & GREET, GOOD
	COMMUNICATION AT ALL TIMES, PINCH POINTS & HAND PLACEMENT, SUSPENDED
	LOADS, LINE OF FIRE, ONE TASK AT A TIME, TRIP HAZARDS, H2S, MUSTER AREA, HOUSE
10/8/2024	KEEPING, UPDATE JSA AS TASK CHANGES
10/8/2024	UNLOAD AND SPOTTED REV PUMP & ASSOCIATED EQUIPMENT
	PERFORM LO/TO ON FLOW LINE VALVES, RD FLOW LINE, UNLOAD & SPOT EQUIPMENT,
10/8/2024	MIRU FALCON RIG #6 & REVERSE UNIT PUMP ASSOCIATED EQUIP
	CHECK PSI ON WELL 2-3/8" PROD TBG = ON VAC, 4-1/2" PROD CSG = 450 PSI, DIG OUT
10/8/2024	CELLAR 8-5/8" INTER CSG = 650 PSI, 13-3/8" SURF CSG = 0 PSI
10/8/2024	SECURE WELL SDFN
10/8/2024	CREW TRAVEL BACK TO MAN CAMP
10/9/2024	CREW TRAVEL TO LOCATION
10/9/2024	HPJSM WITH ALL PERSONAL ON LOCATION
10/9/2024	PERFORMED DAILY START UP RIG INSPECTION
10/9/2024	SET CO/FO & FUNCTION TEST
	CHECK PSI ON WELL 2-3/8" PROD TBG = ON VAC, 4-1/2" PROD CSG = 450 PSI, 8-5/8"
10/9/2024	INTER CSG = 650 PSI, 13-3/8" SURF CSG = 0 PSI
	MIRU PUMP ON 4.5" PROD CSG / RU RESTRAINTS ON ALL IRON / PRESSURE TEST LINES
	TO 1500 PSI W/ A GOOD TEST / OPEN WELL BLEED OFF GAS HEAD F/ ALL STRINGS TO 0
10/9/2024	PSI
	PUMP FW DOWN CSG AFTER 11 BBLS GONE WELL STARTED TO CIRCULATE UP TBG
	(POSSIBLE HOLE ON TBG) CONTINUE PUMPING CIRC 200 BBLS OF FW DOWN CSG OUT
	TBG FOR WELL CONTROL 1.25 BPM @ 450 PSI ISIP = 0 PSI, TBG ON VACUUM / CSG
	STAYED FULL / MONITOR WELL FOR 15 MIN WELL STATIC, NOTE: HAVING ISSUES
	GETTING 10# BW
10/9/2024	FUNCTION TEST BOP W/ A GOOD TEST
	ND 5K PROD TREE, NOTE: TOOK MORE TIME THAN USUAL TO BREAK NUTS F/ WH DUE TO
	RUSTED BOLTS
10/9/2024	NU 5K HYD BOP W/ 5K 2-3/8" PIPE RAMS ON TOP AND 5K BLINDS ON BOTTOM
	RU WORK FLOOR W/ 2-3/8" TBG HANDLING TOOLS, SET UP SAFETY EQUIP, CENTER &
10/9/2024	LEVEL RIG OVER HOLE

	PICK UP ON TBG TO SET TBG SLIPS IN POSITION TBG NEUTRAL WEIGHT @ 48 PTS WORK
	ON GETTING PACKER RELEASE W/ NO LUCK, PICK UP ON 2-3/8" TBG, TURN TBG 1/2 TURN
	TO THE LEFT WORK TBG F/ 44 PTS TO 52 PTS ATTEMPT TO UNJAY F/ ON/OFF TOOL W/
10/9/2024	SAME NEGATIVE RESULTS INSTALL 2-3/8" TIW VALVE, CLOSE BOP
10/9/2024	SECURE WELL SDFN
10/9/2024	CREW TRAVEL BACK TO MAN CAMP
10/10/2024	CREW TRAVEL TO LOCATION
10/10/2024	HPJSM WITH ALL PERSONAL ON LOCATION
10/10/2024	PERFORMED DAILY START UP RIG INSPECTION
10/10/2024	SET CO/FO & FUNCTION TEST
	CHECK PSI ON WELL 2-3/8" PROD TBG = 50 PSI, 4-1/2" PROD CSG = 100 PSI, 8-5/8" INTER
10/10/2024	CSG = 100 PSI, 13-3/8" SURF CSG = 0 PSI
10/10/2024	OPEN WELL TO FLOWBACK TANK BLEED OFF GAS HEAD F/ ALL STRINGS TO 0 PSI
	CONT WORKING TO UNSEAT PROD PACKER USING TBG TONGS WORKING PIPE UP &
	DOWN MULTIPLE TIMES COULD NOT GET PACKER RELEASE OR UNJAY FROM ON/OFF
	TOOL, KEEP WORKING TBG UP & DOWN F/ 44 PTS / 54 PTS / 58 PTS FINALLY GOT PROD
10/10/2024	PACKER RELEASE
10/10/2024	POOH STANDING BACK 75 JTS OF 2-3/8" PROD TBG
10/10/2024	BREAK FOR CREW LUNCH
10/10/2024	PERFORM BOP CLOSING DRILL SECURED WELL, CREW MET @ MUSTER AREA IN 1 MIN
	CONT POOH STANDING BACK 175 JTS OF 2-3/8" PROD TBG (TALLY TBG WHILE POOH)
	NOTE: WE HAD TO POOH SLOW PKR WAS DRAGGING 3 – 5 PTS OVER COMING OUT,
10/10/2024	NSTALL 2-3/8" TIW VALVE, CLOSE BOP
10/10/2024	SECURE WELL SDFN
10/10/2024	CREW TRAVEL BACK TO MAN CAMP
10/11/2024	CREW TRAVEL TO LOCATION
10/11/2024	HPJSM WITH ALL PERSONAL ON LOCATION
10/11/2024	PERFORMED DAILY START UP RIG INSPECTION
10/11/2024	SET CO/FO & FUNCTION TEST
	CHECK PSI ON WELL 2-3/8" PROD TBG = 150 PSI, 4-1/2" PROD CSG = 150 PSI, 8-5/8"
10/11/2024	INTER CSG = 150 PSI, 13-3/8" SURF CSG = 0 PSI
	BLEED OFF GAS HEAD F/ ALL STRINGS TO FLOWBACK TANK, PUMP 30 BBLS DOWN TBG &
10/11/2024	60 BBLS DOWN CSG OF 10# BW FOR WELL CONTROL
	OPEN WELL CONT POOH STANDING BACK 110 JTS OF 2-3/8" PROD TBG, LD ON/OFF
	TOOL, 4.5" PROD PKR W/ 6' X 2-3/8" TBG SUB, (TALLY TBG WHILE POOH / RUN TALLY 4.5"
10/11/2024	PROD PKR WAS SET @ 10,761.32'(TMD) CLOSE BOP
10/11/2024	SECURE WELL SDFW
10/11/2024	CREW TRAVEL BACK HOME
10/14/2024	CREW TRAVEL TO LOCATION
10/14/2024	HPJSM WITH ALL PERSONAL ON LOCATION
10/14/2024	PERFORMED DAILY START UP RIG INSPECTION
10/14/2024	SET CO/FO & FUNCTION TEST

10/14/2024	CHECK PSI ON WELL 4-1/2" PROD CSG = 50 PSI, 8-5/8" INTER CSG = 50 PSI, 13-3/8" SURF CSG = 0 PSI
10/14/2024	BLEED OFF GAS HEAD F/ ALL STRINGS TO 0 PSI, PUMP 50 BBLS DOWN CSG FW FOR WELL
10/14/2024	
10/14/2024	CONTINUE
	MIRU RTX WL, RU PCE, REHEAD WL, MAKE UP & RIH W/ 3.65" OD GR/JB F/ 4.5" CSG 1-
	11/16" WEIGHT BAR W/ CCL TO 10,875' (WMD) W/ NO ISSUES POOH W/ GR/JB FOUND
	FLUID LEVEL @ 1100' (+-) F/ SURF BREAK DOWN GR/JB, MAKE UP 3.58" OD CIBP FOR
	4.5" CSG RIH W/ WL SET 4.5" CIBP @ 10,775' (WMD) W/ NO ISSUES, PULL UP HOLE W/ WL
	100' RBIH TAG CIBP @ 10,775' (WMD) CONFIRMED PLUG SET SUCCESSFULLY, POOH W/
	WL SETTING TOOL, LOAD BACK SIDE W/ 17 BBLS OF FW @ 1.75 BPM MAKE UP &
	CALIBRATE 2.75" OD CBL LOGGING TOOLS AT SURF (ALL GOOD) RIH W/ CBL LOGGING
	TOOLS FOUND FLUID LEVEL @ 50' F/ SURF / TESTED TOOLS @ 1200' F/ SURF CONTINUE
	RIH W/ WL BHA TO 10,775' RUN CBL F/ (10,775' – 0' SURF) (GOOD CMT F/ 10,775' – 9120')
	(SPOTTY CMT F/ 9120' – 8690') (NO CMT F/ 8690' – 7020') (VERY LIGHT CMT F/ 7020' –
	6930') (NO CMT F/ 6930' – 6450') (VERY LIGHT CMT F/ 6450' – 6150') (NO CMT F/ 6150' –
	5320') (VERY SPOTTY CMT F/ 5320' – 3250') (NO CMT F/ 3250' – 290') (NO READINGS F/
40/44/0004	290 – 0' SURF) LD CBL LOGGING TOOLS RDMO RTX WL, NOTE: SEND CBL TO MR. DAVID
10/14/2024	ALVARADO W/ NMOCD FOR REVIEW
	CLOSE BOP. CLOSE 8-5/8" INTER CSG VALVE PRESSURE TEST CIBP & 4.5" PROD CSG TO
40/44/0004	500 PSI HOLD PRESSURE FOR 30 MIN W/ A GOOD TEST / OPEN & CLOSE 8-5/8" INTER
	CSG VALVE AND PRESSURE DROPPED TO 400 PSI AND HOLDING, BLEED OFF PRESSURE
-	SECURE WELL SDFN
-	CREW TRAVEL BACK TO MAN CAMP
-	CREW TRAVEL TO LOCATION
-	HPJSM WITH ALL PERSONAL ON LOCATION
	PERFORMED DAILY START UP RIG INSPECTION
-	SET CO/FO & FUNCTION TEST
10/15/2024	CHECK PSI ON WELL ALL STRINGS = 0 PSI
	OPEN WELL MIRU HYDROSTATIC TUBING TESTERS RIH HYDROTESTING 2-3/8" PROD TBG
	RDMO HYDROSTATIC TBG TESTERS TAG 4.5" CIBP @ 10,753' (TMD) W/ 359 JTS IN THE
10/1-/	HOLE 5' IN ON JT# 360, LD 1 JT (#360) EOT @ 10,748' (TMD) W/ 359 JTS IN THE HOLE,
	CLOSE BOP, INSTALL 2-3/8" TIW VALVE
	SECURE WELL SDFN
	CREW TRAVEL BACK TO MAN CAMP
	CREW TRAVEL TO LOCATION
	HPJSM WITH ALL PERSONAL ON LOCATION
	PERFORMED DAILY START UP RIG INSPECTION
	SET CO/FO & FUNCTION TEST
10/16/2024	CHECK PSI ON WELL ALL STRINGS = 0 PSI

	OPEN WELL MIRU AXIS ENERGY CMT PUMP ON TBG / RU BULK TRK & LOAD BULK TRK W/ 150 SXS CLASS H CMT / RU RESTRAINTS ON ALL IRON / PRESSURE TEST LINES TO 2500 PSI W/ A GOOD TEST / BREAK CIRC W/ 5 BBLS OF 10# BW, CIRC WELL CLEAN W/ 200 BBLS OF 10# BW MIX 30 GAL OF FLEX GEL W/ 150 BBLS OF 10# BW, BREAK CIRC W/ 5 BBLS OF 10# BW, 1ST PLUG) SET 4.5" CIBP @ 10,775' BALANCED PLUG F/ 10,753' – 9058' SPOT 125 SXS CLASS H CMT, 26.27 BBLS SLURRY,15.6# 1.18 YIELD, PLUG CAP 1695' /
10/16/2024	DISPLACE TOC TO 9058' DISPLACE W/ 35.05 BBLS OF 10# BW, RD CMT PUMP
10/16/2024	POOH W/ 30 STANDS LD 57 JTS OF 2-3/8" WS TBG EOT @ 7257' W/ 242 JTS IN THE HOLE, WASH UP PUMP & FLOW BACK PIT, INSTALL 2-3/8" TIW VALVE, CLOSE BOP
	SECURE WELL SDFN
	CREW TRAVEL BACK TO MAN CAMP.
	CREW TRAVEL TO LOCATION
	HPJSM WITH ALL PERSONAL ON LOCATION
	PERFORMED DAILY START UP RIG INSPECTION
	SET CO/FO & FUNCTION TEST
10/17/2024	CHECK PSI ON WELL ALL STRINGS = 0 PSI
10/17/2024	OPEN WELL RIH W/ 2-3/8" WS TBG TAG TOC @ 9880' (TMD) W/ 330 JTS IN THE HOLE 10' IN ON JT# 331, LD 1 JT (#331) PICK UP 10' X 2-3/8" TBG SUB, EOT @ 9880' W/ 330 JTS IN THE HOLE, NOTE: TAG TOC 822' DEEPER / CONTACTED MR. DAVID ALVARADO W/ NMOCD LET HIM KNOW WE TAG TOC 822' DEEPER / NMOCD WANTED TO CONTINUE AS FOLLOWS / SPOT ANOTHER 65 SX CL H CMT 9880' – 8999' WOC – TAG  MIRU AXIS ENERGY CMT PUMP ON TBG / RU BULK TRK & LOAD BULK TRK W/ 150 SXS  CLASS H CMT / RU RESTRAINTS ON ALL IRON / PRESSURE TEST LINES TO 2500 PSI W/ A  GOOD TEST / BREAK CIRC W/ 5 BBLS OF 10# BW 2ND PLUG) BALANCED PLUG F/ 9880' –  8999' SPOT 65 SXS CLASS H CMT, 13.66 BBLS SLURRY,15.6# 1.18 YIELD, PLUG CAP 881' / DISPLACE TOC TO 8999' DISPLACE W/ 34.8 BBLS OF 10# BW RD CMT PUMP, WASH UP
10/17/2024	PUMP & FLOW BACK PIT
	LD 10' X 2-3/8" TBG SUB POOH W/ 15 STANDS LD 28 JTS OF 2-3/8" WS TBG EOT @ 8142'
	W/ 272 JTS IN THE HOLE, INSTALL 2-3/8" TIW VALVE, CLOSE BOP
	SECURE WELL SDFN
	CREW TRAVEL BACK TO MAN CAMP.
	CREW TRAVEL TO LOCATION
	HPJSM WITH ALL PERSONAL ON LOCATION
	PERFORMED DAILY START UP RIG INSPECTION
	SET CO/FO & FUNCTION TEST
10/18/2024	CHECK PSI ON WELL ALL STRINGS = 0 PSI
	OPEN WELL RIH W/ 2-3/8" WS TBG TAG TOC @ 9040' (TMD) W/ 302 JTS IN THE HOLE POOH LD 85 JTS OF 2-3/8" WS TBG EOT @ 6500' W/ 217 JTS IN THE HOLE

	MIRU AXIS ENERGY CMT PUMP ON TBG / RU BULK TRK & LOAD BULK TRK W/ 350 SXS	
CLASS C CMT / RU RESTRAINTS ON ALL IRON / PRESSURE TEST LINES TO 2500 PS		
	GOOD TEST, BREAK CIRC W/ 10 BBLS OF 10# BW, 3TH PLUG) SPACER PLUG BALANCED	
	PLUG F/ 6500' – 6121' SPOT 25 SXS CLASS C CMT, 5.87 BBLS SLURRY,14.8# 1.32 YIELD,	
	379' PLUG CAP / DISPLACE TOC TO 6121' / DISPLACE W/ 23.68 BBLS OF 10# BW NO TAG	
10/18/2024	REQUIRED RD CMT PUMP, WASH UP PUMP & FLOW BACK PIT	
	POOH LD 39 JTS OF 2-3/8" WS TBG EOT @ 5341' W/ 178 JTS IN THE HOLE, INSTALL 2-3/8"	
10/18/2024	TIW VALVE, CLOSE BOP	
10/18/2024	SECURE WELL SDFW	
10/18/2024	CREW TRAVEL BACK HOME.	
10/21/2024	CREW TRAVEL TO LOCATION	
10/21/2024	HPJSM WITH ALL PERSONAL ON LOCATION	
10/21/2024	PERFORMED DAILY START UP RIG INSPECTION	
10/21/2024	SET CO/FO & FUNCTION TEST	
10/21/2024	CHECK PSI ON WELL ALL STRINGS = 0 PSI	
	OPEN WELL CONT POOH STANDING BACK 178 JTS OF 2-3/8" WS TBG BREAK 4' X 2-3/8"	
10/21/2024	PERF TBG SUB	

ON CSG, NOTE: SET PKR & TEST CSG AT MULTIPLE DEPTHS 1) SET PKR @ 308' W/ 10 JTS IN THE HOLE, RU REV PUMP ON 4.5" PROD CSG LOAD BACK SIDE W/ 2 BBLS OF 10# BW PSI 4.5" PROD CSG TO 500 PSI W/ A GOOD TEST / W/ NO LEAK OFF / CSG TESTED GOOD F/ 308' TO 0' (SURF) 2.) UNSEAT PKR RIH & SET PKR @ 906' W/ 30 JTS IN THE HOLE, LOAD BACK SIDE & PSI 4.5" PROD CSG TO 500 PSI W/ A GOOD TEST / W/ NO LEAK OFF / CSG TESTED GOOD F/ 906' TO 0' (SURF) 3.) UNSEAT PKR RIH & SET PKR @ 1508' W/ 50 JTS IN THE HOLE, LOAD BACK SIDE & PSI 4.5" PROD CSG TO 500 PSI W/ A GOOD TEST / W/ NO LEAK OFF / CSG TESTED GOOD F/ 1508' TO 0' (SURF) 4.) UNSEAT PKR RIH & SET PKR @ 2711' W/ 90 JTS IN THE HOLE, LOAD BACK SIDE & PSI 4.5" PROD CSG TO 500 PSI W/ A GOOD TEST / W/ NO LEAK OFF / CSG TESTED GOOD F/ 2711' TO 0' (SURF) 5.) UNSEAT PKR RIH & SET PKR @ 3423' W/ 114 JTS IN THE HOLE, LOAD BACK SIDE & PSI 4.5" PROD CSG TO 500 PSI W/ A GOOD TEST / W/ NO LEAK OFF / CSG TESTED GOOD F/ 3423' TO 0' (SURF) 6.) UNSEAT PKR RIH & SET PKR @ 4031' W/ 134 JTS IN THE HOLE, LOAD BACK SIDE & PSI 4.5" PROD CSG TO 500 PSI W/ A GOOD TEST / W/ NO LEAK OFF / CSG TESTED GOOD F/ 4031' TO 0' (SURF) 7.) UNSEAT PKR RIH & SET PKR @ 5098' W/ 170 JTS IN THE HOLE, LOAD BACK SIDE TRY TO TEST BACK SIDE F/ 5908' - 0' (SURF) PUMP 5 BBLS OF 10# BW GOT INJ -RATE OF 2.5 BPM @ 200 PSI W/ FULL RETURNS ON THE 8-5/8" INTER CSG (FAIL) / RU PUMP ON TBG LOAD TBG TRY TO TEST BELOW PKR PUMP 5 BBLS OF 10# BW GOT INJ -RATE OF 2.5 BPM @ 200 PSI W/ FULL RETURNS ON THE 8-5/8" INTER CSG (FAIL) 8.) UNSEAT PKR RIH & SET PKR @ 5130' W/ 171 JTS IN THE HOLE, RU PUMP ON TBG LOAD TBG PSI TEST BELOW PKR (PROD CSG TO TOC) F/5130' - 6121' TOC TEST TO 500 PSI W/A GOOD TEST BOTTOM HOLE @ 5110' 9.) UNSEAT PKR POOH & SET PKR @ 4893' W/ 163 JTS IN THE HOLE, LOAD BACK SIDE TRY TO TEST BACK SIDE F/ 4893' - 0' (SURF) PUMP 5 BBLS OF 10# BW GOT INJ - RATE 2.5 BPM @ 200 PSI W/ FULL RETURNS ON THE 8-5/8" INTER CSG (FAIL) 10.) UNSEAT PKR LD 1 JT & SET PKR @ 4864' W/ 162 JTS IN THE HOLE, LOAD BACK SIDE & PSI 4.5" PROD CSG TO 500 PSI W/ A GOOD TEST / W/ NO LEAK OFF / CSG 10/21/2024 TESTED GOOD F/ 4864' TO 0' (SURF) TOP OF HOLE @ 4864' FOUND CSG LEAK F/ 4864' MIRU AXIS WL RU PCE, MAKE UP & RIH W/ 1.1' X 1.43" RS, 1.2" X 1-3/8" CCL, 1" X 1-3/8" DOUBLE O-RING TEAR DROP 5" X 1-9/16" FIRING HEAD. 3' X 1-9/16" GUN LOADED 6 SPF W/GEO 2.7G CHARGES, 1.2"X1 9/16" DECENTRALIZER WENT DOWN TO 5425' SHOT 6 SQZ HOLES POOH W/ WL BHA LD GUN VISUAL INPECT GUN & VERIFIED ASF ON DEPTH RDMO 10/21/2024 AXIS WL RU AXIS CMT PUMP ON TBG EST - INJ RATE W/ 10# BW 2.5 BPM @ 600 PSI PUMP 20 BBLS 10/21/2024 OF 10# BW W/ FULL RETURNS ON SURF ON THE 8-5/8" INTER CSG PUMP AHEAD 5 BBLS OF 10# BW 4TH PLUG) PERF @ 5425' SQZ 35 SXS CLASS C CMT, 8.22 BBLS SLURRY,14.8# 1.32 YIELD, 530' PLUG CAP / DISPLACE TOC TO 5300' / 10/21/2024 DISPLACE W/ 22.48 BBLS OF 10# BW, ISIP = 500 PSI 10/21/2024 SECURE WELL SDFN 10/21/2024 CREW TRAVEL BACK TO MAN CAMP 10/22/2024 CREW TRAVEL TO LOCATION 10/22/2024 HPJSM WITH ALL PERSONAL ON LOCATION 10/22/2024 PERFORMED DAILY START UP RIG INSPECTION 10/22/2024 SET CO/FO & FUNCTION TEST 10/22/2024 CHECK PSI ON WELL ALL STRINGS = 0 PSI

	OPEN WELL UNSEAT PKR RIH W/ 2-3/8" WS TBG TAG TOC @ 5290' (TMD) W/ 176 JTS IN	
10/22/2024	THE HOLE 10' IN ON JT# 177	
	POOH W/ 9 STANDS LD 23 JTS OF 2-3/8" WS TBG SET PKR @ 4090' W/ 136 JTS IN THE	
10/22/2024	_	
	MIRU AXIS ENERGY CMT PUMP ON TBG / PRESSURE TEST LINES TO 2500 PSI W/ A GOOD	
	TEST / ESTABLISH INJ – RATE OF 2.5 BPM @ 400 PSI W/ FULL RETURNS ON THE 8-5/8"	
	INTER CSG CIRC A TOTAL OF 70 BBLS OF 10# BW, 4TH PLUG) SQZ CSG LEAK F/ 5110' –	
	4864' SQZ 122 SXS CLASS C CMT, W/ (R-1-11-P 2% CALCIUM CHLORIDE) 28.67 BBLS	
	SLURRY,14.8# 1.32 YIELD, (PLUG CAPACITY 510' / 34 SX / 7.99 BBLS SLURRY IN 4.5"	
	PROD CSG) & (PLUG CAP 510' / 88 SX / 20.68 BBLS SLURRY IN 7-7/8" OPEN HOLE)	
	DISPLACE TOC TO 4600' DISPLACE W/ 23.72 BBLS OF 10# BW, CLOSE 8-5/8" INTER CSG	
10/22/2024	VALVE ISIP = 100 PSI,	
10/22/2024	SECURE WELL WOC TO TAG,	
	CHECK PSI ON WELL ALL STRINGS = 0 PSI OPEN WELL, RU REV PUMP ON TBG LOAD TBG	
	W/ ½ BBL OF 10# BW / PSI TEST SQZ CSG TO 500 PSI HOLD PRESSURE F/ 15 MIN W/ A	
10/22/2024	GOOD TEST W/ NO LEAK OFF BLEED OF PRESSURE	
	UNSEAT PKR RIH W/ 2-3/8" WS TBG TAG TOC @ 4630' (TMD) W/ 154 JTS IN THE HOLE 10'	
10/22/2024	IN ON JT# 155	
10/22/2024	POOH W/ 7 STANDS LD 49 JTS OF 2-3/8" WS TBG SET PKR @ 2770' W/ 92 JTS IN THE HOLE	
	MIRU AXIS WL RU PCE, MAKE UP & RIH W/ 1.1' X 1.43" RS, 1.2" X 1-3/8" CCL, 1" X 1-3/8"	
	DOUBLE O-RING TEAR DROP 5" X 1-9/16" FIRING HEAD, 3' X 1-9/16" GUN LOADED 6 SPF	
	W/GEO 2.7G CHARGES, 1.2"X1 9/16" DECENTRALIZER WENT DOWN TO 3300' SHOT 6 SQZ	
	HOLES POOH W/ WL BHA LD GUN VISUAL INPECT GUN & VERIFIED ASF ON DEPTH RDMO	
10/22/2024	AXIS WL	
	RU AXIS CMT PUMP ON TBG / PRESSURE TEST LINES / ESTABLISH INJ – RATE OF 2.5 BPM @	
	400 PSI W/ FULL RETURNS ON THE 8-5/8" INTER CSG CIRC A TOTAL OF 75 BBLS OF 10#	
	BW, 5TH PLUG) PERF @ 3300' SQZ 35 SXS CLASS C CMT, 8.22 BBLS SLURRY,14.8# 1.32	
	YIELD, 530' PLUG CAP / DISPLACE TOC TO 3175' / DISPLACE W/ 16.98 BBLS OF 10# BW,	
10/22/2024	ISIP = 200 PSI RD CMT PUMP	
10/22/2024	SECURE WELL SDFN	
10/22/2024	CREW TRAVEL BACK TO MAN CAMP	
10/23/2024	CREW TRAVEL TO LOCATION	
10/23/2024	HPJSM WITH ALL PERSONAL ON LOCATION	
	PERFORMED DAILY START UP RIG INSPECTION	
10/23/2024	SET CO/FO & FUNCTION TEST	
10/23/2024	CHECK PSI ON WELL ALL STRINGS = 0 PSI	
	UNSEAT PKR RIH W/ 2-3/8" WS TBG TAG TOC @ 3150' (TMD) W/ 104 JTS IN THE HOLE 25'	
10/23/2024	IN ON JT# 105	
10/23/2024	POOH W/ 8 STANDS LD 55 JTS OF 2-3/8" WS TBG SET PKR @ 1028' W/ 34 JTS IN THE HOLE	
	MIRU AXIS WL RU PCE, MAKE UP & RIH W/ BHA TO 1585' SHOT 6 SQZ HOLES POOH W/ WL	
10/23/2024	BHA LD GUN VERIFIED ASF RD WL	

RU AXIS CMT PUMP ON TBG / PSI TEST LINES / EST INJ - RATE 2.2 BPM @ 850 PSI W/ FULL
RETURNS ON THE 8-5/8" INTER CSG CIRC A TOTAL OF 70 BBLS OF 10# BW 7TH PLUG)
PERF @ 1585' SQZ 35 SXS CLASS C CMT, W/ (R-1-11-P 2% CALCIUM CHLORIDE) 8.22
BBLS SLURRY,14.8# 1.32 YIELD, (PLUG CAPACITY 125' / 8.21 SX / 1.93 BBLS SLURRY IN
4.5" PROD CSG) & (PLUG CAPACITY 125' / 26.79 SX / 6.29 BBLS SLURRY IN 8-5/8" INTER
CSG) / DISPLACE TOC TO 1460' / DISPLACE W/ 10.65 BBLS OF 10# BW, ISIP = 800 PSI RD
10/23/2024 CMT PUMP
10/23/2024 SECURE WELL WOC TO TAG,
CHECK PSI ON WELL ALL STRINGS = 0 PSI OPEN WELL, UNSEAT PKR RIH W/ 2-3/8" WS
10/23/2024 TBG TAG TOC @ 1440' (TMD) W/ 48 JTS IN THE HOLE 5' IN ON JT# 49
10/23/2024 POOH LD 48 JTS OF 2-3/8" WS TBG SET PKR @ 35' W/ 1 JT IN THE HOLE
MIRU AXIS WL RU PCE, MAKE UP & RIH W/ BHA TO 425' SHOT 6 SQZ HOLES POOH W/ WL
10/23/2024 BHA LD GUN VERIFIED ASF RDMO AXIS WL
RU AXIS CMT PUMP ON TBG / EST INJ – RATE 2.5 BPM @ 200 PSI W/ FULL RETURNS ON 8-
10/23/2024 5/8" INTER CSG / CIRC 30 BBLS 10# BW RD PUMP
10/23/2024 SECURE WELL SDFN
10/23/2024 CREW TRAVEL BACK TO MAN CAMP
10/24/2024 CREW TRAVEL TO LOCATION
10/24/2024 HPJSM WITH ALL PERSONAL ON LOCATION
10/24/2024 PERFORMED DAILY START UP RIG INSPECTION
10/24/2024 SET CO/FO & FUNCTION TEST
10/24/2024 CHECK PSI ON WELL ALL STRINGS = 0 PSI
OPEN WELL RU AXIS CMT PUMP ON TBG / PSI TEST LINES / EST INJ – RATE 2.5 BPM @ 200
PSI PUMP 25 BBLS OF 10# BW W/ FULL RETURNS ON SURF ON THE 8-5/8" INTER CSG, RD
10/24/2024 PUMP
10/24/2024 UNSEAT & LD 4.5" 32-A PKR
10/24/2024 RD WORK FLOOR & ASSOCIATED EQUIP
10/24/2024 ND 5K HYD BOP
10/24/2024 NU 3K X 7-1/16" B-1 WH FLANGE
RU CMT PUMP ON 4.5" PROD CSG BREAK CIRC W/ 10 BBLS 10# BW, 8TH PLUG) PERF @
425' SQZ 120 SXS CLASS C CMT, W/ (R-1-11-P 2% CALCIUM CHLORIDE) 28.21 BBLS
SLURRY, 14.8# 1.32 YIELD (PLUG CAPACITY 425' / 28 SX / 6.58 BBLS SLURRY IN 4.5" PROD
CSG) & (PLUG CAPACITY 425' / 92 SX / 21.62 BBLS SLURRY IN 8-5/8" INTER CSG) F/ 425' -
0' (SURF) GOT FULL RETURNS ON 8-5/8" INTER CSG CLOSE VALVE AND LEFT 500 PSI ON
PROD CSG, WOC TOP OFF HOLE W/ CMT VERIFY CMT AT SURF / HOOK UP ON THE 13-3/8'
SURF CSG TOP OFF 13-3/8" SURF CSG W/ 15 SXS CLASS C CMT, 3.52 BBLS, 14.8# 1.32
YIELD PLUG CAP 41.5' PRESSURE UP TO 500 PSI W/ NO LEAK OFF, CLOSE VALVE LEFT 500
10/24/2024 PSI ON SURF CSG, ISIP = 500 PSI ON ALL STRINGS, WASH UP PUMP & FLOW BACK PIT
RDMO PU (FALCON RIG #6 ) & REV UNIT PUMP & P&A PUMP ASSO EQUIP, CLEAN LOC P&A
JOB COMPLETED (WELL READY FOR CUT & CAP) STAGED ALL EQUIP TO SIDE OF LOC
10/24/2024 READY TO MOVE TO NEXT LOCATION, SDFN
10/24/2024 CREW TRAVEL BACK TO MAN CAMP

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory <a href="https://www.emnrd.nm.gov/ocd/contact-us">https://www.emnrd.nm.gov/ocd/contact-us</a>

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 410303

# **CONDITIONS**

Operator:	OGRID:
OXY USA WTP LIMITED PARTNERSHIP	192463
P.O. Box 4294	Action Number:
Houston, TX 772104294	410303
	Action Type:
	[C-103] Sub. Plugging (C-103P)

# CONDITIONS

Created By	Condition	Condition Date
gcordero	Clean Location in accordance with 19.15.25.10 NMAC.	12/13/2024
gcordero	Submit C-103Q within one year of plugging.	12/13/2024