

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Oxy USA	API Number 30-015-30605
Property Name Pure Gold B Federal	Well No 20

1. Surface Location								
Lot - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
D	20	23S	31E	1260	S	250	E	Eddy

Well Status							
TA'D WELL	YES	NO	SHUT-IN	YES	NO	INJ	DATE
							12/9/2024

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	○	○	/	○	Vac
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Isolated for
Water	Y/N	Y/N	Y/N	Y/N	Waterhead if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

This is a retest to confirm well has good mechanical integrity and is cleared to be injected into

BI-T- Passed

Signature 	OIL CONSERVATION DIVISION
Printed name Jerry Burton	Entered into RBDMS
Title Surface Specialist	Re-test
E-mail Address Jerry-burton@oxy.com	
Date 12-9-24	
Phone 505-241-1063	
Witness 	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 410619

CONDITIONS

Operator: OCCIDENTAL PERMIAN LTD P.O. Box 4294 Houston, TX 772104294	OGRID: 157984
	Action Number: 410619
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/16/2024