hone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

| DRADENIIEAD TEST REFORT | | | | | | | | | | | |
|---|------------|--------------|--------------|-------|----------------|-----|-----------|------------------|------------------------|---------------|---------------|
| Operator Name TEAM OPERATING | | | | | | | | , | 30-025-10476 | | |
| Property Name LANGLIE MATTIX PENROSE SAND UNIT | | | | | | | | | Well No. 221 | | |
| ⁷ Surface Location | | | | | | | | | | | |
| UL - Lot L | Section 27 | Township 22S | Range 37E | | Feet from 1980 | N/S | Line S | Feet From 660 | | E/W Line W | County LEA |
| Well Status | | | | | | | | | | | |
| YES TA'D | WELL | O (YES | SHUT-IN | NO IN | INJECTOR | SWD | OIL | RODUCER (| GAS | | DATE 6/2024 |
| | | | | | | | | | | | |

OBSERVED DATA

| | (A)Surface | (B)Interm(1) | (C)Interm(2) | (D)Prod Csng | (E)Tubing |
|----------------------|------------|--------------|--------------|--------------|----------------------------|
| Pressure | (A) | | | Ø | 240 |
| Flow Characteristics | | | | | |
| Puff | Y / 🕥 | Y / N | Y / N | ⊘ / N | CO2 _ |
| Steady Flow | Y / 🖎 | Y/N | Y/N | Y / 🖎 | WTR X |
| Surges | Y / 🖎 | Y / N | X / N | Y / (N) | Type of Fluid |
| Down to nothing | Y N | Y / N | Y / N | (Y)/ N | Injected for Waterflood if |
| Gas or Oil | Y / 🚫 | Y / N | Y / N | Y / N | applies. |
| Water | Y / N | Y / N | Y / N | Y / (N) | |

| Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies. | | | | | | |
|--|--|--|--|--|--|--|
| Temperature of the string (1997) and the str | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |
| | | | | | | |

| Sign | nature: Aust In | luser | OIL CONSERVATION DIVISION |
|-------|-------------------------------|-----------------------|---------------------------|
| Prin | ited name: AUSTIN L. MUSGRAV | Е | Entered into RBDMS |
| Γitle | e: FIELD SUPERVISOR | | Re-test |
| E-m | nail Address: AUSTIN.MUSGRAVI | E@TEAMOPERATING.COM | |
| Date | · 108/26/2024 | Phone: (432) 701-5144 | |
| | | Witness: | |
| | | | |

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 411398

CONDITIONS

| Operator: | OGRID: |
|------------------------|--|
| TEAM OPERATING, L.L.C. | 332148 |
| PO Box 835 | Action Number: |
| Pinehurst, TX 77362 | 411398 |
| | Action Type: |
| | [UF-BHT] Bradenhead Test (BRADENHEAD TEST) |

CONDITIONS

| Crea By | ated | Condition | Condition Date |
|------------|-------|-----------|----------------|
| kfc | rtner | None | 12/16/2024 |