hone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico

Energy, Minerals and Natural Resources DepartmentOil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

	DRADENIEAD TEST REFORT											
Operator Name TEAM OPERATING								,	³ API Number 30-025-10497			
Property Name LANGLIE MATTIX PENROSE SAND UNIT									Well No. 243			
	7. Surface Location											
UL - Lot	Section	Township	Range		Feet from	N/	S Line	Feet From	T	E/W Line	County	
J	28	22S	37E		2310		S	2310		E	LEA	
Well Status												
YES TA'D	WELL N	O VES	SHUT-IN	NO	INJECTOF INJ	SWD	OIL)	PRODUCER	GAS		DATE 12024	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	Ø			30	Ø
Flow Characteristics					
Puff	(Y)/ N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / Ň	Y/N	Y/N	Y / N	GAS
Surges	Y / 🕥	/Y / N	Y / N	Y / N	Type of Fluid
Down to nothing	Y N	Y / N	Y / N	Y / N	Injected for Waterflood if
Gas or Oil	Y / Ň	Y / N	Y / N	Y / N	applies.
Water	Y / N	Y / N	Y / N	Y / N	

П	Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.
Н	
Н	
П	
П	
Н	
Н	
Н	
Н	
П	

lignature:	Muser	OIL CONSERVATION DIVISION
'rinted name: AUSTIN L. MUSGR	AVE	Entered into RBDMS
'itle: FIELD SUPERVISOR		Re-test
E-mail Address: AUSTIN.MUSGRA	AVE@TEAMOPERATING.COM	
Date: 08/30/2024	Phone: (432) 701-5144	
	Witness:	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 411402

CONDITIONS

Operator:	OGRID:
TEAM OPERATING, L.L.C.	332148
PO Box 835	Action Number:
Pinehurst, TX 77362	411402
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/16/2024