1 strict 1 25 N. French Dr., Hobbs, NM 88240 1 ione: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

DRADENIEAD TEST REFORT										
Operator Name TEAM OPERATING								30-025-12739		
Property Name LANGLIE MATTIX PENROSE SAND UNIT							V	Well No. 365		
7. Surface Location										
UL - Lot	Section 34	Township 22S	Range 37E		Feet from 1320	N/S Line N	Feet From 1320	E/W Line E	County LEA	
Well Status										
YES TA'D	WELL N	O YES	SHUT-IN	NO IN.	INJECTOR J	SWD OI	PRODUCER G	AS 09/0	DATE DZ / 2024	
								•		

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
ressure	0			10	35
low Characteristics					
Puff	(Y) / N	Y / N	Y / N	Y / N	CO2 WTR
Steady Flow	Y / 🕥	Y/N	Y/N	Y / N	GAS GAS
Surges	Y / 🕥	X / N	Ý/N	Y / N	Type of Fluid
Down to nothing	(Y) N	Y / N	Y / N	Y / N	Injected for Waterflood if
Gas or Oil	Y / 🕥	Y / N	Y / N	Y / N	applies.
Water	Y / (N)	Y / N	Y / N	Y / N	

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.					
	-				

Signature: Quest of M	usg	OIL CONSERVATION DIVISION
rinted name: AUSTIN L. MUSGRA	AVE	Entered into RBDMS
Title: FIELD SUPERVISOR		Re-test
E-mail Address: AUSTIN.MUSGRA	VE@TEAMOPERATING.COM	
Date: 09/02/2024	Phone: (432) 701-5144	
	Witness:	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 411431

CONDITIONS

Operator:	OGRID:
TEAM OPERATING, L.L.C.	332148
PO Box 835	Action Number:
Pinehurst, TX 77362	411431
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/16/2024