

District 1

625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

| | | | |
|--|--|-----------------------------------|--|
| Operator Name TEAM OPERATING | | API Number 30-025-22655 | |
| Property Name LANGLIE MATTIX PENROSE SAND UNIT | | Well No. 323 | |

7. Surface Location

| | | | | | | | | |
|----------------------|----------------------|------------------------|---------------------|--------------------------|----------------------|-------------------------|----------------------|----------------------|
| UL - Lot E | Section 33 | Township 22S | Range 37E | Feet from 1790 | N/S Line N | Feet From 660 | E/W Line W | County LEA |
|----------------------|----------------------|------------------------|---------------------|--------------------------|----------------------|-------------------------|----------------------|----------------------|



Well Status

| | | | | | | |
|--|--|-----------------|-----|--|-----|---------------------------|
| TA'D WELL YES <input checked="" type="radio"/> NO | SHUT-IN YES <input checked="" type="radio"/> NO | INJECTOR INJ | SWD | PRODUCER <input checked="" type="radio"/> OIL | GAS | DATE 08/30/2024 |
|--|--|-----------------|-----|--|-----|---------------------------|

OBSERVED DATA

| | (A)Surface | (B)Interm(1) | (C)Interm(2) | (D)Prod Csg | (E)Tubing |
|----------------------|--|--------------|--------------|-------------|---------------|
| Pressure | 7 | | | 10 | 45 |
| Flow Characteristics | | | | | |
| Puff | Y / <input checked="" type="radio"/> N | Y / N | Y / N | Y / N | CO2 ___ |
| Steady Flow | Y / <input checked="" type="radio"/> N | Y / N | Y / N | Y / N | WTR ___ |
| Surges | Y / <input checked="" type="radio"/> N | Y / N | Y / N | Y / N | GAS ___ |
| Down to nothing | <input checked="" type="radio"/> Y / N | Y / N | Y / N | Y / N | Type of Fluid |
| Gas or Oil | Y / <input checked="" type="radio"/> N | Y / N | Y / N | Y / N | Injected for |
| Water | Y / <input checked="" type="radio"/> N | Y / N | Y / N | Y / N | Waterflood if |
| | | | | | applies |

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

| | | | |
|--|-----------------------|---|--|
| Signature:  | | OIL CONSERVATION DIVISION | |
| Printed name: AUSTIN L. MUSGRAVE | | Entered into RBDMS | |
| Title: FIELD SUPERVISOR | | Re-test  | |
| E-mail Address: AUSTIN.MUSGRAVE@TEAMOPERATING.COM | | | |
| Date: 08/30/2024 | Phone: (432) 701-5144 | | |
| Witness: | | | |

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oecd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 411425

CONDITIONS

| | |
|--|--|
| Operator: TEAM OPERATING, L.L.C. PO Box 835 Pinehurst, TX 77362 | OGRID: 332148 |
| | Action Number: 411425 |
| | Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST) |

CONDITIONS

| Created By | Condition | Condition Date |
|------------|-----------|----------------|
| kfortner | None | 12/16/2024 |