istrict 1 325 N. French Dr., Hobbs, NM 88240 none: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico Energy, Minerals and Natural Resources Department

Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

BRADENHEAD TEST REPORT											
Operator Name TEAM OPERATING							,	30-025-09659			
Property Name COOPER JAL UNIT									Well No. 238		
⁷ Surface Location											
UL - Lot	Section 25	Township 24S	Range 36E		Feet from 1980		Line	Feet From		E/W Line W	County LEA
Well Status											
YES SHUT-IN NO INJ INJECTOR SWD OIL GAS OF 129/2024											

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	(2)	0		0	200
Flow Characteristics					CO2
Puff	Y / 🕥	Y / 🕦	Y / N	(Y)/ N	WTR 😕
Steady Flow	Y / (N)	Y / 🕥	Y/N	Y / (N)	GAS
Surges	Y / 🚫	Y / 🕥	/Y / N	Y/(N)	Type of Fluid
Down to nothing	(Y)/ N	(Y) / N	/ Y / N	(Y) N	Injected for Waterflood if
Gas or Oil	Y / (N)	Y / (N)	Y / N	Y / (N)	applies.
Water	Y / N	Y / (N)	Y / N	Y /(N)	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

OIL CONSERVATION DIVISION			
Entered into RBDMS			
Re-test			
V \\			

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 412333

CONDITIONS

Operator:	OGRID:
TEAM OPERATING, L.L.C.	332148
PO Box 835	Action Number:
Pinehurst, TX 77362	412333
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/17/2024