District 1 625 N. French Dr., Hobbs, NM 88240 hone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

DRADENHEAD TEST REPORT												
Operator Name TEAM OPERATING									API Number 30-025-10603			
Property Name SKELLY PENROSE A UNIT								Well No. 22				
7. Surface Location												
UL - Lot E	Section 03	Township 23S	Range 37E		Feet from 1980	N/S	Line N	Feet From 660	E/W Li		ounty LEA	
Well Status												
YES TA'D	WELL	O YES	SHUT-IN	NO IN.	INJECTOR J	SWD	OIL PR	ODUCER G.	AS OG	DATE 1/03/201	24	

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
ressure	Ø			15	45
low Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / (N)	Y/N	Y/N	Y / N	WTR_
Surges	Y / 🕥	X / N	X/N	Y / N	GAS
Down to nothing	Ý N	Y / N	/ Y / N	Y / N	Injected for Waterflood if
Gas or Oil	Y / (N)	Y / N	Y / N	Y / N	applies.
Water	Y / (N)	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

ignature Quant 1	Musg	OIL CONSERVATION DIVISION
rinted name: AUSTIN L. MUSGF	RAVE	Entered into RBDMS
'itle: FIELD SUPERVISOR		Re-test
-mail Address: AUSTIN.MUSGR	AVE@TEAMOPERATING.COM	
Date: 09/03/2024	Phone: (432) 701-5144	,
	Witness:	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 411542

CONDITIONS

Operator:	OGRID:
TEAM OPERATING, L.L.C.	332148
PO Box 835	Action Number:
Pinehurst, TX 77362	411542
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/17/2024