hone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

DRADENHEAD TEST REPORT									
Operator Name TEAM OPERATING								³ API Number 30-025-10621	
Property Name SKELLY PENROSE A UNIT						W	Well No. 35		
	7 Surface Location								
UL - Lot	Section	Township	Range		Feet from	N/S Line	Feet From	E/W Line	County
0	04	23S	37E		660	5	1980	E	LEA
Well Status									
YES TA'D	WELL N	O YES	SHUT-IN	NO INJ	INJECTOR	swd Oil	PRODUCER GA	s 09/03	DATE 3/2024

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
ressure	Ø			35	45
Flow Characteristics					
Puff	Y / 🖎	Y / X	Y / N	Y / N	CO2
Steady Flow	Y / 🕟	Y/N	Y/N	Y / N	WTR GAS
Surges	Y / 🕥	/Y / N	/Y / N	Y / N	Type of Fluid
Down to nothing	(Y)/ N	Y / N	Y / N	Y / N	Injected for Waterflood if
Gas or Oil	Y/N	Y / N	Y / N	Y / N	applies.
Water	Y / (N)	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.	

ignature: Ous & M	usq	OIL CONSERVATION DIVISION
rinted name: AUSTIN L. MUSGRAVI	3	Entered into RBDMS
itle: FIELD SUPERVISOR		Re-test Q
-mail Address: AUSTIN.MUSGRAVE	@TEAMOPERATING.COM	9
Vate: 09/03/2024	Phone: (432) 701-5144	
,	Witness:	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 411548

CONDITIONS

Operator:	OGRID:
TEAM OPERATING, L.L.C.	332148
PO Box 835	Action Number:
Pinehurst, TX 77362	411548
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/17/2024