istrict <u>1</u> 525 N. French Dr., Hobbs, NM 88240 hone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name										
TEAM OPERATING								30-025-10706		
Property Name SKELLY PENROSE A UNIT									Well No. 42	
	7. Surface Location									
UL - Lot B	Section 10	Township 23S	Range 37E		Feet from 660	N/S Lin	e	Feet From 1980	E/W Line	County LEA
Well Status										
YES	WELL	O YES	SHUT-IN	NO INJ	INJECTOR	SWD	PRO OIL	ODUCER GA		DATE 3/2024

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
ressure	0	(7)		/×	1500
ow Characteristics					1300
Puff	Y / 🕥	Y / 🕥	Y / Ŋ	(Ŷ) N	CO2
Steady Flow	Y / (N)	Y / (N)	Y // N	Y / (N)	₩TR <u>×</u>
Surges	Y / (N)	Y / 🕥	X/N	Y/N	GAS
Down to nothing	(Y) N	(Y)/ N	Y / N	Y) N	Type of Fluid Injected for
Gas or Oil	Y / (N)	Y / (N)	Y / N	Y / (N)	Waterflood if applies.
Water	Y / (N)	Y / (N)	Y / N	Y / (N)	-

D	moules Please state formach of the A. D. G. D. C. D. C
K	marks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.
ы	
ш	

Sig nature III	lung	OIL CONSERVATION DIVISION
Pri ted name: AUSTIN L. MUSG	RAVE	Entered into RBDMS
Tit e: FIELD SUPERVISOR		Re-test
E-i iail Address: AUSTIN.MUSGR	RAVE@TEAMOPERATING.COM	13
Da 2: 09/03/2024	Phone: (432) 701-5144	
	Witness:	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 411551

CONDITIONS

Operator:	OGRID:
TEAM OPERATING, L.L.C.	332148
PO Box 835	Action Number:
Pinehurst, TX 77362	411551
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/17/2024