

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Midland	API Number 30-015-11347
Property Name LMWU	Well No. # 125

2. Surface Location

UL - Lot B	Section 34	Township 24S	Range 37E	Feet from 660	NS Line N	Feet from 1980	EW Line E	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	---------------------	--------------------------	---------------------	----------------------

Well Status

TA'D WELL YES	NO	YES	SHUT-IN NO	INJ	INJECTOR SWD	OIL	PRODUCER GAS	DATE 11-12-24
------------------	----	-----	---------------	-----	-----------------	-----	-----------------	-------------------------


OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csmg	(E) Tubing
Pressure	0			0	250
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ☒
Surges	Y/N	Y/N	Y/N	Y/N	GAS ☐
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Field
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Isolated for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					Applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Well is NOT T/A'd
Well is disconnected

Signature:	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date:	
Phone:	
Witness: Kay Rolon	



Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 411863

CONDITIONS

Operator: MIDLAND OPERATING INC. P.O. Box 52308 Midland, TX 79710	OGRID: 148981
	Action Number: 411863
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/17/2024