

Division 1
1625 N. French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Ext. (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CROSS TIMBER ENERGY, LLC	API Number 30-025-23566
Property Name NORTH VACUUM UNIT	Well No 142

1. Surface Location									
U. - Lot J	Section 14	Township 17S	Range 34E		Feet from 1807	N/S Line FSL	Feet from 1880	E/W Line FEL	County LEA

Well Status									
T&D WELL YES	NO	YES	SHUT-IN NO	INJ	INJECTOR NO	SWD NO	OIL NO	PRODUCER N/A	GAS NO
									DATE 5-24-24

OBSERVED DATA

	(A) Surface	(B) Interf (1)	(C) Interf (2)	(D) Prod Csg	(E) Tubing
Pressure	0	NA	NA	0	0
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid injected for wellbore cleanout
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Well down due to down hole packer leaky

FAIL

Signature <i>Roy Caudillo</i>	OIL CONSERVATION DIVISION	
Printed name ROY CAUDILLO	Entered into RBDMS	
Title LEASE OPERATOR	Re-test	
E-mail Address rcaudillo@ctfieldsvcs.com		
Date 5-24-24	Phone 1-575-659-9866	
Witness		

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 412511

CONDITIONS

Operator: CROSS TIMBERS ENERGY, LLC 400 West 7th Street Fort Worth, TX 76102	OGRID: 298299
	Action Number: 412511
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/17/2024