

District I
1425 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Seely Oil Company		API Number 30-025-24939	
Property Name EK Penrose Sand Unit		Well No. #802	

Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
N	20	18S	34E	330	S	1650	W	Lea

Well Status

TA'D WELL YES	SHUT-IN YES	INJECTOR (INJ)	PRODUCER OIL	DATE 7-29-24
------------------	----------------	-------------------	-----------------	-----------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	NA	NA	0	1800
Flow Characteristics					
Puff	Y / (N)	Y / N	Y / N	Y / (N)	CO2
Steady Flow	Y / (N)	Y / N	Y / N	Y / (N)	WTR ✓
Surges	Y / (N)	Y / N	Y / N	Y / (N)	GAS —
Down to nothing	(Y) / N	Y / N	Y / N	(Y) / N	Type of Fluid Injected for Waterflood if applies.
Gas or Oil	Y / (N)	Y / N	Y / N	Y / (N)	
Water	Y / (N)	Y / N	Y / N	Y / (N)	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Mike Frasier		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date: 7-29-24	Phone:		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM

GR

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 376856

CONDITIONS

Operator: SEELY OIL CO 815 W 10th Street Ft. Worth, TX 76102	OGRID: 20497
	Action Number: 376856
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/17/2024