

District 1
125 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

| | |
|---|-----------------------------------|
| Operator Name TEAM OPERATING | API Number 30-025-33786 |
| Property Name SKELLY PENROSE A UNIT | Well No. 84 |

7. Surface Location

| | | | | | | | | |
|----------------------|----------------------|------------------------|---------------------|--------------------------|----------------------|------------------------|----------------------|----------------------|
| UL - Lot I | Section 04 | Township 23S | Range 37E | Feet from 2637 | N/S Line S | Feet From 92 | E/W Line E | County LEA |
|----------------------|----------------------|------------------------|---------------------|--------------------------|----------------------|------------------------|----------------------|----------------------|



Well Status

| | | | | | | | | |
|-------------------------|-----------|-----------------------|-----------|------------------|-----------------------|------------------------|------------------|---------------------------|
| TA'D WELL YES | NO | SHUT-IN YES | NO | INJ NO | INJECTOR NO | PRODUCER OIL | GAS NO | DATE 09/04/2024 |
|-------------------------|-----------|-----------------------|-----------|------------------|-----------------------|------------------------|------------------|---------------------------|

OBSERVED DATA

| | (A)Surface | (B)Interm(1) | (C)Interm(2) | (D)Prod Csng | (E)Tubing |
|----------------------|--------------|--------------|--------------|--------------|---------------|
| Pressure | 17 | | | 40 | 120 |
| Flow Characteristics | | | | | |
| Puff | Y / N | Y / N | Y / N | Y / N | CO2 ___ |
| Steady Flow | Y / N | Y / N | Y / N | Y / N | WTR ___ |
| Surges | Y / N | Y / N | Y / N | Y / N | GAS ___ |
| Down to nothing | Y / N | Y / N | Y / N | Y / N | Type of Fluid |
| Gas or Oil | Y / N | Y / N | Y / N | Y / N | Injected for |
| Water | Y / N | Y / N | Y / N | Y / N | Waterflood if |
| | | | | | applies. |

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

| | |
|--|---|
| Signature:  | OIL CONSERVATION DIVISION |
| Printed name: AUSTIN L. MUSGRAVE | Entered into RBDMS |
| Title: FIELD SUPERVISOR | Re-test  |
| E-mail Address: AUSTIN.MUSGRAVE@TEAMOPERATING.COM | |
| Date: 09/04/2024 | Phone: (432) 701-5144 |
| | Witness: |

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 411527

CONDITIONS

| | |
|--|--|
| Operator: TEAM OPERATING, L.L.C. PO Box 835 Pinehurst, TX 77362 | OGRID: 332148 |
| | Action Number: 411527 |
| | Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST) |

CONDITIONS

| Created By | Condition | Condition Date |
|------------|-----------|----------------|
| kfortner | None | 12/17/2024 |