Dis ict 1 N. French Dr., Hobbs, NM 88240 Phr e: (575) 393-6161 Fax: (575) 393-0720

# State of New Mexico

# Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

RRADENHEAD TEST REPORT

	Operator Name TEAM OPERATING									30-025-33945 Well No.			
	Property Name SKELLY PENROSE A UNIT							88					
_	7 Surface Location												
Γ	UL - Lot	Section 03	Township 23S	Range 37E			Feet from 1308	N/5	S Line S	Feet From 2502		E/W Line E	County LEA
-	Well Status												
~	TA'D	WELL N	o (YES	SHUT-IN	NO	INJ	INJECTOR	SWD	OIL PI	RODUCER	GAS	09/04	DATE 12024

# OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
l ressure	0			Ø	NA
low Characteristics					CO2
Puff	Y / 🕥	Y / N	Y / N	Y / 🕥	WTR_
Steady Flow	Y / 🚫	Y/N	Y/N	Y/N	GAS
Surges	Y / 🕥	Y/N	X / N	Y / N	Type of Fluid
Down to nothing	(y) / N	Y / N	Y / N	(y)/ N	Injected for Waterflood if
Gas or Oil	Y / (N)	Y / N	Y / N	Y /(N)	applies.
Water	Y / (N)	Y / N	Y / N	Y / (N)	

temarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

ignature: Out IN	Turan	OIL CONSERVATION DIVISION
rinted name: AUSTIN L. MUSGR	AVE	Entered into RBDMS
itle: FIELD SUPERVISOR		Re-test
:-mail Address: AUSTIN.MUSGRA	AVE@TEAMOPERATING.COM	Se .
Date: 09/04/2024	Phone: (432) 701-5144	7
	Witness:	

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 411517

## **CONDITIONS**

Operator:	OGRID:
TEAM OPERATING, L.L.C.	332148
PO Box 835	Action Number:
Pinehurst, TX 77362	411517
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

## CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/17/2024