

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0726

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Seely Oil Company		API Number 30-025-35000	
Property Name EK Queen Unit		Well No. #010	

1 Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
I	13	18S	33E	1650	S	330	E	Lea

Well Status

TA'D WELL YES	☒ NO	SHUT-IN YES	☒ NO	INJECTOR ☒ INJ	SWD	PRODUCER OIL	GAS	DATE 7-29-24
------------------	-------------------------------------	----------------	-------------------------------------	--	-----	-----------------	-----	-----------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	cemented	NA	NA	0	2000
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / ☒ N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / N	Y / N	Y / N	Y / ☒ N	GAS
Down to nothing	Y / N	Y / N	Y / N	☒ Y / N	Type of Fluid Injected for Waterflood if applies
Gas or Oil	Y / N	Y / N	Y / N	Y / ☒ N	
Water	Y / N	Y / N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: Mike Frasier		OIL CONSERVATION DIVISION	
Printed name:		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date: 7-29-24	Phone:		
Witness:			

INSTRUCTIONS ON BACK OF THIS FORM

GR

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 376846

CONDITIONS

Operator: SEELY OIL CO 815 W 10th Street Ft. Worth, TX 76102	OGRID: 20497
	Action Number: 376846
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/17/2024