




South District - Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

BRADENHEAD TEST REPORT

Operator Name K&M Resources LLC	API Number 30-015-10087
Property Name North Benson Queen Unit	Well No 016

Surface Location

U.L. - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
J	18S	30E	28	1650	S	1651	E	Eddy

28 18S 30E TH Well Status

TA'D WELL	SHUT-IN	INJECTOR	PRODUCER	DATE
YES ☒ NO	YES ☒ NO	☒ INJ	☐ OIL ☐ GAS	4/30/24

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0	0		0	520
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	CO2 WTR ✓ GAS Type of fluid Subjected for Waterflooded systems
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Down to nothing	☒ Y / N	☒ Y / N	Y / N	☒ Y / N	
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BHT-OK

Signature: Travis Herron Printed name: Travis Herron Title: Operator E-mail Address: Travis.herron@Mail.com Date: 4/30/24 Phone: 575 616-1645 Witness: Barbara [Signature]	OIL CONSERVATION DIVISION Entered into RBDMS Re-test
--	---

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 378021

CONDITIONS

Operator: K&M RESOURCES LLC P.O. Box 1540 Artesia, NM 88211	OGRID: 330662
	Action Number: 378021
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/19/2024