

South District - Artesia

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

BRADENHEAD TEST REPORT

Operator Name K&M Resources LLC	API Number 30-015-10906
Property Name North Benson Queen unit	Well No. 042

Surface Location					
UT - Lot 4	Section 32	Township 18S	Range 30E	Feet from 1980	N/S Line N
				Feet from 1980	E/W Line W
					County Eddy

Well Status				DATE	
YES	TA'D WELL (NO)	YES	SHUT-IN (NO)	INJECTOR (NO)	PRODUCER (NO)
				SWD	GAS
					4/30/24

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	0			0	360
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ✓
Surges	Y / N	Y / N	Y / N	Y / N	GAS
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of fluid injected for waterflood cycles
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BHT-OK

Signature Travis Herron	OIL CONSERVATION DIVISION
Printed name: Travis Herron	Entered into RBDMS
Title Operator	Re-test
E-mail Address: Travis.herron@Mqil.com	
Date: 4/30/24	
Phone: 575 616 1645	
Witness: Barbara Yohel	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 377579

CONDITIONS

Operator: K&M RESOURCES LLC P.O. Box 1540 Artesia, NM 88211	OGRID: 330662
	Action Number: 377579
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/19/2024