

District I
1622 N French Dr, Hobbs, NM 88240
Phone (575) 393-6161 Fax (575) 393-6720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CROSS TIMBER ENERGY, LLC		API Number 30-025-25096
Property Name NORTH VACUUM ABO UNIT		Well No 224

1. Surface Location								
UT - Lat B	Section 11	Township 17S	Range 34E	Feet from 745	NS Line FNL	Feet From 1880	EAV Line FEL	County LEA

Well Status							
YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR NO	PRODUCER NO	DATE 12-16-24

OBSERVED DATA

	(A) Surface	(B) Interwell (1)	(C) Interwell (2)	(D) Prod Casing	(E) Tubing
Pressure	0	0		0	4000
Flow Characteristics					
Puff	Y N	Y N	Y N	Y N	CO2
Steady Flow	Y N	Y N	Y N	Y N	WTR ✓
Surges	Y N	Y N	Y N	Y N	GAS
Down to nothing	Y N	Y N	Y N	Y N	Type of Fluid
Gas or Oil	Y N	Y N	Y N	Y N	Isolated for
Water	Y N	Y N	Y N	Y N	Washed if

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

C39 Strings read marked.

Signature		OIL CONSERVATION DIVISION	
Printed name		Entered into RBDMS	
Title		Re-test	
E-mail Address			
Date	Phone		
Witness	<i>Shay Polson</i>		

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 414024

CONDITIONS

Operator: CROSS TIMBERS ENERGY, LLC 400 West 7th Street Fort Worth, TX 76102	OGRID: 298299
	Action Number: 414024
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
kfortner	None	12/26/2024