State Of New Mexico Energy, Minerals and Natural Resources Department

09-Jan-25

LOGOS OPERATING, LLC

Pre Enforcement Notification

2010 Afton Place Farmington, NM 87401

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-039-26463] ROSA UNIT #181		OGRID: 289408	K-11-31N-06W 2445 FSL 1415 FV	K-11-31N-06W 2445 FSL 1415 FWL	
n Date	Type Inspection	Inspector	Inspection N	Inspection No.	
25	Routine Inspection	[TV] Thomas Vermersch	iTV25938624	4	
		Title		Corrective Action Due	
cTV25962718 19.15.16.8 Sign on Wells Inaccurate Information				4/9/2025	
cTV25962719 19.15.17 Pits, Closed-Loop Systems, Below Grade Tanks and Sumps Noncompliance with Requirements (Construction, Operations or Closure)				4/9/2025	
(The base o	of below grade tank is not fu	lly visible and needs dug out a	all the way around.)		
cTV25962720 19.15.29 Releases Surface Leaks/Spills				4/9/2025	
			<u> </u>	? There is also some	
	19.15.16.8 \$ (Unit letter of 19.15.17 Pit (Construction) (The base of 19.15.29 Ref.)	Type Inspection Routine Inspection Routine Inspection 19.15.16.8 Sign on Wells Inaccurate Info (Unit letter on sign has faded and is no: 19.15.17 Pits, Closed-Loop Systems, B. (Construction, Operations or Closure) (The base of below grade tank is not fu 19.15.29 Releases Surface Leaks/Spills (Staining around the base of below gra	Type Inspection Inspector Routine Inspection [TV] Thomas Vermersch Title 19.15.16.8 Sign on Wells Inaccurate Information (Unit letter on sign has faded and is not legible. Well sign was fixed s 19.15.17 Pits, Closed-Loop Systems, Below Grade Tanks and Sumps (Construction, Operations or Closure) (The base of below grade tank is not fully visible and needs dug out a 19.15.29 Releases Surface Leaks/Spills (Staining around the base of below grade tank that needs cleaned up	Title 19.15.16.8 Sign on Wells Inaccurate Information (Unit letter on sign has faded and is not legible. Well sign was fixed same day.) 19.15.17 Pits, Closed-Loop Systems, Below Grade Tanks and Sumps Noncompliance with Requirements (Construction, Operations or Closure) (The base of below grade tank is not fully visible and needs dug out all the way around.)	

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.