

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT			
Operator Name		API Number	
CROSS TIMBER ENERGY, LLC		30-025-23568	
Property Name		Well No	
NORTH VACUUM ABO UNIT		145	

Surface Location									
UL - Lot	Section	Township	Range		Feet from	NS Line	Feet From	E/W Line	County
P	27	17S	34E		660	FSL	860	FEL	LEA

TADWELL	SHUT-IN	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE
YES NO	YES NO	YES NO					12-16-24

	(A)Surface	(B)Interf#1	(C)Interf#2	(D)Prod Csg	(E)Tubing
Pressure	-0-	n/a	n/a	-0-	4200
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ✓
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Exposed to
Water	Y/N	Y/N	Y/N	Y/N	Waterwork H applied

BIT.OIC

Signature 		OIL CONSERVATION DIVISION	
Printed name. <u>R. Bennett</u>		Entered into RBDMS	
Title		Re-test	
E-mail Address			
Date <u>12-16-24</u>	Phone		
	Witness <u>Barbara Underk</u>		

Released to Imaging: 1/29/2025 10:43:21 AM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 415244

CONDITIONS

Operator: CROSS TIMBERS ENERGY, LLC 400 West 7th Street Fort Worth, TX 76102	OGRID: 298299
	Action Number: 415244
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
blydick	None	1/29/2025