

Dugan 1

1035 N French Dr, Elletts, NM 87240
Phone (505) 397-6151 Fax (505) 397-0220State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name CROSS TIMBER ENERGY, LLC		API Number 30-025-28739
Property Name NORTH VACUUM UNIT		Well No 257

Surface Location									
U.L. - Lot E	Section 13	Township 17S	Range 34E	Feet from 1980	NS Line ENL	Feet From 739	EAW Line FWL	County LEA	

Well Status									
YES	PA'D WELL (NO)	YES	SHUT-IN (NO)	INJ	INJECTOR	SWD	(OIL)	PRODUCER	GAS
									DATE 5-24-24

OBSERVED DATA

	(A) Surface	(B) Interp (1)	(C) Interp (2)	(D) Prod Casing	(E) Tubing
Pressure	0	NA	NA	40	150
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Entered for
Water	Y/N	Y/N	Y/N	Y/N	Waterhead if
					applied

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature <i>Roy Caudillo</i>		OIL CONSERVATION DIVISION	
Printed name ROY CAUDILLO		Entered into RBDMS	
Title LEASE OPERATOR		Re-test	
E-mail Address rcaudillo@ctfieldsvcs.com			
Date 5-24-24	Phone 1-575-659-9866		
Witness			

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 416068

CONDITIONS

Operator: CROSS TIMBERS ENERGY, LLC 400 West 7th Street Fort Worth, TX 76102	OGRID: 298299
	Action Number: 416068
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
blydick	None	2/4/2025