State of New Mexico

Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Morr	Operator 1		30-025 31816						
Vacuum Gloneta Wast Unit					Sylvell No.				
¹ Surface Location									
-UL-Lot Section Township Range Feet from N/S Line				eet From E/W	Line County				
Well Status Lea									
YES TA'D WELL NO	YES SHUT-IN	NO INJ INJECTOR	SWD OIL PROI	DUCER GAS	1/21/2025				
OBSERVED DATA									
	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing				
Pressure		/ .	/						
Flow Characteristics									
Puff	YN	Y/N/	Y/N/	Y / (1	WTD				
Steady Flow	Y (N)	Y/N	Y //N	Y / (1	GAS				
Surges	Y/N	Y/N	Y// N	Y / (T	T) pe of Fluid				
Down to nothing	(Y) N	N Y/N	/Y / N	(1)	Waterflood if				
Gas or Oil	Y /(P)	Y/N	/ Y / N	Y //					
Water	Y-(-N')	/ Y / N	Y/N	Y / 1	8)				
Remarks - Please state for each	th string (A,B,C,D,E) per	tinent information regarding blee	d down or continuous bui	ld up if applies.					
Signature				OIL CONSERV	VATION DIVISION				
Printed name:				Entered into RBDMS					
Title				Re-test					
E-mail Address:			I CO-1						
Date:	Phone:	7							
	1 10110	V							

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 424033

CONDITIONS

Operator:	OGRID:	
MorningStar Operating LLC	330132	
400 W 7th St	Action Number:	
Fort Worth, TX 76102	424033	
	Action Type:	
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)	

CONDITIONS

Created By	Condition	Condition Date
blydick	None	2/4/2025