OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date o	f Test_	12,	15/2	4	Oper	ator_Maralex Res	ources_API #	#30-045- <u>23</u>	3 <i>9 }</i>	<u>.</u>
Proper	tv Nar	ne Da	me Fa	decal W	/ell No	Location	· Unit 2 Sect	tion A Towns	hin 271/Dana	e <u>/3C</u>
Well S	tatus(S	Shut-In	or Prod	ucing) Ini	tial PSI:	Tubing 150 Inte	ermediate	_ Casing [🖒]	Bradenhead_	0
OPE	N BRA	DENH	EAD AN	D INTERI	MEDIAT	TE TO ATMOSPHI	ERE INDIVID	UALLY FOR 15	MINUTES EA	ACH
Testing	BH_	Braden Int	PRESSU head . Csg	JRE INTEF Int	≷M Csg		FLOW BRADENHE	CHARACTERIS EAD INTERM		
TIME 5 min_	O		10			- Steady Flow_				
10 min_	0		10	,		Surges				
15 min_	0		10			Down to Noth	ning		· .	
20 min_						Nothing	/			
25 min_					·i	Gas			· 	
30 min_		-				Gas & Water_				
				·		Water				
If brade	nhead f	lowed w	ater, chec	k all of the	descript	ions that apply belo	<u>w:</u>	1		
1	CLEAR		FRESH	SA	ALTY	SULFUR	BLACK	 -		
5 MINU	ΓΕ SHU	JT-IN P	RESSUR	E B)	RADENI	head 🔘	INTERMED	DIATE		
REMARI	KS:									
				-		. ,				
Ву	*	m.	j Ha	ne_		Witness_				
Mechanie (Pumpe Position				-					
E-mail ad	dress									

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 409756

CONDITIONS

Operator:	OGRID:
MARALEX RESOURCES INC	13998
P.O. Box 338	Action Number:
Ignacio, CO 81137	409756
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By		Condition Date
smcfall	None	2/27/2025