

District 1
1625 N French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax: (575) 393-0120

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING, LLC		API Number 30-025-25730
Property Name CENTRAL VACUUM UNIT		Well No 82

1. Surface Location									
UL - Lot K	Section 36	Township 17S	Range 34E	Feet from 1333	N/S Line FSL	Feet From 2528	E/W Line FWL	County LEA	

Well Status									
TA'D WELL YES	NO	YES	SHUT-IN NO	NO	INJECTOR INJ	SWD	OIL	PRODUCER GAS	DATE 5 FEB 25

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Csg	(E) Tubing
Pressure	0	0	N/A	0	1390
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR -
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid Inferred for Waterflood if applies
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

INJ CO2

Signature Van Riper		OIL CONSERVATION DIVISION	
Printed name: Van Riper Tyrone		Entered into RBDMS	
Title Lease OP		Re-test	
E-mail Address: TVenriper@ctfieldsevs.com			
Date: 5 FEB 25	Phone: 505.491.9775		
Witness			

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 441138

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 441138
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
blydick	None	4/22/2025