



# NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4/2/25 Operator San Juan Resources API # 30-039-60020

Property Name CLARK #002 Location: Unit P Section 5 Township 24N Range 03W  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 59 Intermediate N/A Casing 110 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time.	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	110	N/A	N/A	N/A	Steady Flow	N/A
10 minutes	0	110				Surges	
15 minutes	0	110				Down to Nothing	
20 minutes						No Flow	X
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	0	110				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate N/A

REMARKS: Bradenhead had 0 psi. No build up pressure

By Wyatt Templeton Witness \_\_\_\_\_  
Lease Operator  
(Position)

NMOCD Test Area:

1

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 455015

CONDITIONS

Operator:  SAN JUAN RESOURCES, INC. 1499 Blake St, #10C Denver, CO 80202	OGRID:  20208
	Action Number:  455015
	Action Type:  [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	5/7/2025