State Of New Mexico Energy, Minerals and Natural Resources Department

12-May-25

Coterra Energy Operating Co.

Pre Enforcement Notification

6001 Deauville Blvd 300N Midland, TX 79706

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-015-45436] CABRERA 34 FEDERAL #001H OGRID: 215099 H-34-26S-27E 1110 FSL 270 FEL

Inspection DateType InspectionInspectorInspection No.5/12/2025Routine Inspection[RA] Robert AsheriRA2513239441ViolationTitleCorrective Action Due

cRA2513257715 19.15.16.8 Sign on Wells Inaccurate Information

8/10/2025

(Well sign at the well head and production equipment does not reflect new operator (Coterra Energy Operating Co.).)

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.