

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 320-0243 File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

(Submit 1 copy to doove address)				
Date of Test 8/5/25 Operator Benson Montin Green API #30-039-00540				
Property Name Cou Well No. O Location: Unit O Section 9 Township 26NRange w				
Well Status(Shut-In or Producing) Initial PSI: Tubing 43 Intermediate Casing 17 Bradenhead O				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRESSURE FLOW CHARACTERISTICS Testing Bradenhead INTERM BRADENHEAD INTERMEDIATE BH Int Csg Int Csg				
TIME 5 min 0 17 D 17 Steady Flow				
10 min 0 17 0 17 Surges				
15 min 0 18 0 18 Down to Nothing				
20 min Nothing X X				
25 min Gas_				
30 min Gas & Water				
Water				
If bradenhead flowed water, check all of the descriptions that apply below:				
CLEAR FRESH SALTY SULFUR BLACK				
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE O				
By furi Velogry Witness				
E-mail address				

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 494753

CONDITIONS

Operator:	OGRID:
BENSON-MONTIN-GREER DRILLING CORP	2096
4900 College Blvd.	Action Number:
Farmington, NM 87402	494753
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By		Condition Date
tvermersch	None	9/8/2025