

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

(Subilit 1 C	copy to above address)				
Date of Test_8/5/25 Operator	Benson Montia Greer API #30-0 39-05997				
Property Name COU Well No. 07	Z Location: Unit <u>K. Section 13</u> Township <u>25 N</u> Range 1 w				
Well Status(Shut-In on Producing) Initial PSI: Tubing 20 Intermediate 0 Casing 15 Bradenhead 0					
OPEN BRADENHEAD AND INTERMEDIATE TO	OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH				
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE				
TIME 5 min 0 15 0 15	Steady Flow				
10 min 0 15 0 15	Surges				
15 min 0 15 0 15	Down to Nothing				
20 min	Nothing X X				
25 min	Gas				
30 min_	Gas & Water				
	Water				
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY	SULFURBLACK				
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE C					
By few Usbor of W Lease operator (Position)	/itness				
E-mail address					

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 494757

CONDITIONS

Operator:	OGRID:
BENSON-MONTIN-GREER DRILLING CORP	2096
4900 College Blvd.	Action Number:
Farmington, NM 87402	494757
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	9/8/2025