

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test_	7/24/25	Operato	Benson Montin Greet API #30-039-20325				
			4 Location: Unit <u>C</u> Section <u>34</u> Township <u>25N</u> Range 1 W				
Well Status(S	Shut-In or Pro	ducing) Initial PSI: T	ubing 56 Intermediate Casing 20 Bradenhead				
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH							
Testing BH	PRESS Bradenhead Int Csg	SURE INTERM Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE				
TIME 5 min 0	20		Steady Flow				
10 min 0	20		Surges				
15 min 0	21		Down to Nothing				
20 min			Nothing X				
25 min_			Gas				
30 min			Gas & Water				
			Water				
If bradenhead flowed water, check all of the descriptions that apply below:							
CLEAR FRESH SALTY SULFUR BLACK							
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE							
REMARKS:							
hease operator Witness							
Lease Operator (Position)							
E-mail address	s						

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 494769

CONDITIONS

Operator:	OGRID:
BENSON-MONTIN-GREER DRILLING CORP	2096
4900 College Blvd.	Action Number:
Farmington, NM 87402	494769
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	9/8/2025