

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/5/25 Operator Benson Montin Greet API #30-039-2035Z										
Property Name Cou Well No. 17 Location: Unit Cz Section Township 24NRange Iw										
Well Status(Shut-In or Producing) Initial PSI: Tubing 144 Intermediate O Casing 164 Bradenhead O										
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH										
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg			1	FLOW CHA BRADENHEAD	RACTERISTICS INTERMEDIATE					
TIME 5 min 0	164	0 /	164	Steady Flow						
10 min 0	164	0	164	Surges						
15 min Ö	164	0	164	Down to Nothin	.g		2			
20 min				Nothing	X	X				
25 min				Gas						
30 min				Gas & Water		***				
				Water						
If bradenhead flowed water, check all of the descriptions that apply below:										
CLEAR FRESH SALTY SULFUR BLACK										
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE O										
By Burn Velagra Witness Witness										
(Position)										
E-mail address										

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 494778

CONDITIONS

Operator:	OGRID:
BENSON-MONTIN-GREER DRILLING CORP	2096
4900 College Blvd.	Action Number:
Farmington, NM 87402	494778
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Create	ed By	Condition	Condition Date
tveri	mersch	None	9/8/2025