



BRADENHEAD TEST REPORT

Date of Test 6-28-25 Operator AWC API #30-0 39-21579
Property Name Chacon Well No. 1 Location: Unit P Section 30 Township 24N Range 83W
Well Status(Shut-In or Producing) Producing Initial PSI: Tubing 0 Intermediate 0 Casing 0 Bradenhead 0

PRESSURE

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		0		
10 min	0		0		
15 min	0		0		
20 min	0				
25 min					
30 min					

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 

INTERMEDIATE

REMARKS:

Braden Head Opst-5 min Shut in Opst-Stop Test

By

Witness

(Position)

E-mail address _____

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 495745

CONDITIONS

Operator: ADVANCED WIRELESS COMMUNICATIONS, L.L.C. 24 Road 1956 Farmington, NM 87401	OGRID: 371710
	Action Number: 495745
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	9/8/2025