



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-16-25 Operator Rm Operative API #30-0 39-23740

Property Name Solera Well No. 11 Location: Unit C Section 22 Township 25N Range 6W

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate N/A Casing 60 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	<u>0</u>		<u>60</u>		
10 min	<u>0</u>		<u>60</u>		
15 min	<u>0</u>		<u>60</u>		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>✓</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

By Terry Pearson
Pumper
(Position)

Witness _____

E-mail address _____

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 477745

CONDITIONS

Operator: RIM OPERATING, INC. 5 Inverness Drive East Englewood, CO 80112	OGRID: 372497
	Action Number: 477745
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	9/8/2025