

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

		(Submit 1	copy to doors			
Date of Test_	7/30/25	Operator	BensonMon	in Green API#	30-0 <u>39<i>-23830</i></u>	
Property Nan	ne Cou	Well No2:	8Location:	Unit B Section	29 Township 23 N Ran	ge IW
Well Status(S	Shut-In or Produ	cing) Initial PSI: Tu	bing 45 Inter	rmediate Ca	sing 26 Bradenhead	0
OPEN BRA	ADENHEAD AN	D INTERMEDIATE	TO ATMOSPHE	ERE INDIVIDUAL	LY FOR 15 MINUTES	EACH
Testing BH	PRESSU Bradenhead Int Csg	RE INTERM Int Csg	* *	FLOW CHA BRADENHEAD	ARACTERISTICS INTERMEDIATE	_
TIME 5 min 0	20		Steady Flow_			_
10 min 0	20		Surges			-
15 min 0	22		Down to Notl	ning		_
20 min			Nothing	Х		_
25 min			Gas			
30 min			Gas & Water			_
			Water			_
If bradenhead	flowed water, che	ck all of the descriptio	ns that apply bel	ow:		
CLEA	RFRESH	SALTY	SULFUR	BLACK		
5 MINUTE SE	HUT-IN PRESSUE	RE BRADENHE	EAD	INTERMEDIA	TE	
hease (Posi	illelarge Operator	7	Witness			
E-mail address						

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 494785

CONDITIONS

Operator:	OGRID:
BENSON-MONTIN-GREER DRILLING CORP	2096
4900 College Blvd.	Action Number:
Farmington, NM 87402	494785
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	9/8/2025