

# NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 320-0243
File Via OCD Permitting

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/31/25 Operator Benson Montin Greer API #30-0 39-24505					
Property Name Cou Well No. 43 Location: Unit H Section 8 Township 28 N Range W					
Well Status(Shut-In or Producing) Initial PSI: Tubing 34 Intermediate Casing 18 Bradenhead 0					
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH					
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE				
TIME 5 min 0 18	Steady Flow				
10 min 0 18	Surges				
15 min 0 19	Down to Nothing				
20 min	Nothing X				
25 min	Gas				
30 min	Gas & Water				
	Water				
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY	SULFUR BLACK				
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE REMARKS:					
By Benne Velosy Witness					
By Benne Velocay Witness					
E-mail address					

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 494793

### **CONDITIONS**

Operator:	OGRID:
BENSON-MONTIN-GREER DRILLING CORP	2096
4900 College Blvd.	Action Number:
Farmington, NM 87402	494793
	Action Type:
	[UF-BHT] Bradenhead Test (BRADENHEAD TEST)

## CONDITIONS

Create	ed By	Condition	Condition Date
tveri	mersch	None	9/8/2025