



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4-22-2025 Operator NueVida Resources API # 30-039-24793

Property Name 29-4 CARSON 12 #001 Location: Unit H Section 12 Township 29N Range 04W
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 689 Intermediate NA Casing 689 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate Flowed Flowed	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	Ø	689	N A	N A	N A	Steady Flow	
10 minutes	Ø	689				Surges	
15 minutes	Ø	689				Down to Nothing	
20 minutes						No Flow	XX N A
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI	Ø	689				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead Ø Intermediate NA

REMARKS:

THIS IS A FREE FLOWING WELL. WELL IS SHUT IN

OPENED BH - NOTHING

By SCOTT RODGERS
LEASE OPERATOR

(Position)

Witness _____

NMOCD Test Area:

1

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 455717

CONDITIONS

Operator: NueVida Resources, LLC 5950 Cedar Springs Road Dallas, TX 75235	OGRID: 328537
	Action Number: 455717
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	9/8/2025