



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4-22-2025 Operator NueVida Resources API # 30-039-25068
Property Name 29-4 CARSON 3 #001 Location: Unit D Section 3 Township 29N Range 04W
(Well Name and Number)
Pressure (Shut-in or Producing) 573 Tubing 573 Intermediate NA Casing 573 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	Ø	573	N A	N A	A	Steady Flow	N A
10 minutes	Ø	573				Surges	
15 minutes	Ø	573				Down to Nothing	
20 minutes	Ø	573				No Flow	
25 minutes	Ø	573				Gas	
30 minutes	Ø	573				Gas and Water	
5 minute SI	Ø	573				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead Ø Intermediate NA

REMARKS:

STOP Clocked WELL, WELL IS SHUT IN

OPENED BH- SHORT SOFT PUFF DOWN TO NOTHING IN 1 SECOND. NO H₂S DETECTED (4 GAS MONITOR)

By SCOTT ROGERS
LEASE OPERATOR

(Position)

Witness _____

NMOCD Test Area:

1

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 455716

CONDITIONS

Operator: NueVida Resources, LLC 5950 Cedar Springs Road Dallas, TX 75235	OGRID: 328537
	Action Number: 455716
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	9/8/2025