



# NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 320-0243  
File Via OCD Permitting

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/29/25 Operator Benson Montin Greer API #30-0 39-25713  
Property Name COU Well No. 45 Location: Unit N Section 28 Township 25N Range 1W  
Well Status (Shut-In or Producing) Initial PSI: Tubing 50 Intermediate      Casing 32 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>32</u>		
10 min	<u>0</u>		<u>32</u>		
15 min	<u>0</u>		<u>33</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>    </u>	<u>    </u>
Surges <u>    </u>	<u>    </u>
Down to Nothing <u>    </u>	<u>    </u>
Nothing <u>    </u>	<u>X</u>
Gas <u>    </u>	<u>    </u>
Gas & Water <u>    </u>	<u>    </u>
Water <u>    </u>	<u>    </u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE     

REMARKS:

By Benni Veloz  
Lease operator  
(Position)

Witness     

E-mail address

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 494796

CONDITIONS

Operator: BENSON-MONTIN-GREER DRILLING CORP 4900 College Blvd. Farmington, NM 87402	OGRID: 2096
	Action Number: 494796
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
tvermersch	None	9/8/2025