

Santa Fe Main Office
Phone: (505) 476-3441
General Information
Phone: (505) 629-6116

Online Phone Directory Visit:
<https://www.emnrd.nm.gov/ocd/contact-us/>

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

<p>SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p> <p>1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other</p> <p>2. Name of Operator Mewbourne Oil Company</p> <p>3. Address of Operator P.O. Box 5270 Hobbs, NM 88241</p> <p>4. Well Location Unit Letter O : 990 feet from the South line and 1650 feet from the East line Section 29 Township 18S Range 28E NMPM Eddy County</p>		<p>WELL API NO. 30-015-02110</p> <p>5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/></p> <p>6. State Oil & Gas Lease No.</p> <p>7. Lease Name or Unit Agreement Name Resler Yates State</p> <p>8. Well Number #343</p> <p>9. OGRID Number 14744</p> <p>10. Pool name or Wildcat (3230) Artesia; Queen-Grayburg-San Andres</p>
		11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK PLUG AND ABANDON
TEMPORARILY ABANDON CHANGE PLANS
PULL OR ALTER CASING MULTIPLE COMPL
DOWNHOLE COMMINGLE
CLOSED-LOOP SYSTEM
OTHER:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING
COMMENCE DRILLING OPNS. P AND A
CASING/CEMENT JOB

OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Please see attached procedure & wellbore schematics

Spud Date: Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE TITLE **Regulatory Specialist**DATE **1/16/26**Type or print name **John Harrison**
For State Use OnlyE-mail address: **john.harrison@mewbourne.com**PHONE: **575-393-5905**

APPROVED BY: _____ TITLE: _____ DATE: _____
Conditions of Approval (if any):



MOC P&A Summary

Well Name: RESLER YATES STATE 343 P&A (SANDLOTT
API#:3001502110
ENERGY) SLO
Job Category: P&A
Start Date: 11/17/2025
Contact Name: Joel Aranda
Company: GSM Consulting
11/17/2025

Operations Summary

MIRU P&A rig & equipment. Dig out WH. SWI. SDFD due to high winds.

11/18/2025

Operations Summary

TP 0#. CP 0#. Unhung rods & pulled back pumping unit. POOH w/58- 3/4" rods. Attempt to ND WH. PU on tbg & csg traveling also. Unscrewed 4 1/2" WH. POOH w/ 48 jts 2 3/8" tbgs & SN w/ standing valve (tbgs dragging up hole). MIRU WL. RIH w/gauge ring & could not work past 491'. POOH w/WL. RIH w/3 7/8" mill & tbgs. Tagged @ 491' & worked past tight spot w/tongs. Left EOT @ 504'. SWI. SDFD.

11/19/2025

Operations Summary

SITP 0#. CP 0#. POOH w/tbg & flat bottom mill. NU 4 1/2" collar, flange w/ ball valves & BOP. RIH w/ 3 7/8" flat bottom mill. Tagged @ 113'. Could not work past while working w/tongs. POOH w/tbg & mill (found formation mud around mill). RIH w/ tbgs open ended. Tagged @ 118'. Fell through to 125'. Could not work past. PU on BOP w/winch line while attempting to work tbgs downhole w/no success. POOH w/ tbgs. RIH w/ mule shoe. Could not work past 125'. POOH w/tbg (found core of formation inside mule shoe). RIH w/bent mule shoe. Could not work past 125'. POOH. Dig deeper around WH & found surface csg collar parted. SWI. SDFD

11/20/2025

Operations Summary

CP 0#. RIH w/bent mule shoe & tagged @ 125'. Attempt to work past while working BOP w/no success. POOH w/tbg & mule shoe (found core of formation inside mule shoe). RIH w/mule shoe & worked past 125'. Continued RIH & tagged solid @ 1516'. Unable to work past. Pumped 56 BFW down tbgs to break circulation pumping 2.5 BPM @ 200#. Attempt to work past 1516' w/ no success. Pumped 31 BFW to break circulation. Spotted 15 sacks class C cmt followed by 4.9 BFW displacement. POOH w/ 14 stds 2 3/8" tbgs. SWI. SDFD.

11/21/2025

Operations Summary

SITP 0#. CP 0#. RIH w/tbg & tagged TOC @ 1438'. POOH w/tbg & perfed csg @ 980'. RIH w/tbg & left EOT @ 1038'. Pumped 45 BFW to break circulation. Spotted 50 sacks class C cmt followed by 3 BFW displacement. POOH w/tbg to 183'. WOC. RIH w/tbg & tagged TOC @ 892'. POOH w/tbg to 183'. SWI. SDFWE.

11/24/2025

Operations Summary

SITP 0#. SICP 0#. RIH w/ tbgs & tag TOC @ 857' (7 Rivers top @ 930'). POOH to 630'. RU WL & RIH w/ perf guns. Perf @ 628'. Pumped 75 sks class C cmt & displaced w/1.7 BFW. POOH w/tbg & leave EOT @ 163'. WOC. RIH w/tbg to 672'. Did not tag TOC. Pumped 75 sks class C cmt & displaced w/1.7 BFW. POOH w/tbg. Left EOT @ 163'. SWI & SDFD.

11/25/2025

Operations Summary

SITP 0#. SICP 0#. RIH w/tbg & tagged TOC @ 600'. Perforated csg @ 600'. POOH & LD tbgs & mule shoe. ND BOP. NU B1 flange. Pumped total of 850 sacks class C cmt to circulate cmt to surface. SWI. SDFD

12/1/2025

Operations Summary

SICP 0#. ND B1 flange. NU BOP. RIH w/tbg & tagged @ 120'. POOH w/tbg & found cmt inside EOT. MIRU WL & perfed csg @ 110'. POOH w/WL. Attempted to break circulation w/120 BFW w/no success. Pulled 4 pts into WH (found cmt behind 4 1/2" csg). RIH w/4 jts 2 3/8" tbgs. SWI & SDFD.

12/2/2025


Operations Summary

SITP 0#. SICP 0#. Pumped 4 bbls LCM to establish circulation. Shut csg in & injected 10 bbls LCM into perfs. Opened csg & circulated an additional 2 bbls LCM followed by 100 sacks class C cmt to get cmt to surface. POOH & LD tbgs. ND BOP. Top filled csg w/8 sacks class C cmt & WOC. RDMD P&A rig & equipment. Well P&A'd effective 12/02/2025.

Resler Yates State #343 – As Plugged

990' FSL & 1650' FEL, Sec. 29 – T18S – R28E - Eddy Co, NM

API 30-015-02110





Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 544002

CONDITIONS

Operator: MEWBOURNE OIL CO P.O. Box 5270 Hobbs, NM 88241	OGRID: 14744
	Action Number: 544002
	Action Type: [C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By	Condition	Condition Date
loren.diede	None	1/20/2026