



NEW MEXICO DEPARTMENT OF REVENUE
 1125 TULSA AVE. S.W. ALBUQUERQUE, NM 87102-1125

OIL CONSERVATION DIVISION
 AZTEC DISTRICT OFFICE
 1000 RIO BRAZOS ROAD
 AZTEC NM 87410
 (505) 334-5179 FAX: (505) 331-6170
 http://oildata.state.nm.us/oed/District/862/index.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 11-19-25 Operator Wapiti Operating LLC API # 3010 07-28801

Property Name VPR A Well No. 262 Location: Unit 4 Section 13 Township 13N Range 119E

Well Status (Shut-In or Producing) Initial PSI: Tubing 160 Intermediate N/A Casing 6 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	N/A	6	N/A	N/A
10 min	0		6		
15 min	0		6		
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		N/A
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Nothing on BH

By Monty Colangelo

Witness _____

Operator II

(Position)

E-mail address mcolangelo@wapitienergy.com

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 532886

CONDITIONS

Operator: Wapiti Operating, LLC 1251 Lumpkin Rd Houston, TX 77043	OGRID: 328741
	Action Number: 532886
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
smcfall	None	1/26/2026