

District 1  
1625 N. French Dr., Hobbs, NM 88240  
Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

## BRADENHEAD TEST REPORT

Operator Name <b>Scout Energy Management LLC.</b>	API Number <b>30-025-12293</b>
Property Name <b>WEST Dollarchide Drinkard Unit</b>	Well No. <b>#066</b>

## 2. Surface Location

UL - Lot <b>K</b>	Section <b>31</b>	Township <b>24S</b>	Range <b>38E</b>	Feet from <b>2312</b>	N/S Line <b>FSL</b>	Feet From <b>2309</b>	E/W Line <b>FWL</b>	County <b>LCA</b>
----------------------	----------------------	------------------------	---------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------


## Well Status

TA'D WELL YES <input type="radio"/> NO <input checked="" type="radio"/>	SHUT-IN YES <input type="radio"/> NO <input checked="" type="radio"/>	INJECTOR <input checked="" type="radio"/> INJ <input type="radio"/> SWD	PRODUCER OIL <input type="radio"/> GAS <input type="radio"/>	DATE <b>3-13-25</b>
--	--	--	---	------------------------

## OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	<b>0</b>	<b>0</b>		<b>0</b>	<b>1250</b>
Flow Characteristics					
Puff	<b>Y / N</b>	<b>Y / N</b>	<b>Y / N</b>	<b>Y / N</b>	CO2 <input checked="" type="checkbox"/>
Steady Flow	<b>Y / N</b>	<b>Y / N</b>	<b>Y / N</b>	<b>Y / N</b>	WTR <input checked="" type="checkbox"/>
Surges	<b>Y / N</b>	<b>Y / N</b>	<b>Y / N</b>	<b>Y / N</b>	GAS <input type="checkbox"/>
Down to nothing	<b>Y / N</b>	<b>Y / N</b>	<b>Y / N</b>	<b>Y / N</b>	Type of Fluid Exposed for Weathered & spikes
Gas or Oil	<b>Y / N</b>	<b>Y / N</b>	<b>Y / N</b>	<b>Y / N</b>	
Water	<b>Y / N</b>	<b>Y / N</b>	<b>Y / N</b>	<b>Y / N</b>	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: <b>Lee Ellison</b>	Entered into RBDMS
Title: <b>SR. Prod Foreman</b>	Re-test
E-mail Address: <b>lellison@scoutep.com</b>	
Date: <b>3-13-25</b>	
Phone: <b>806-891-0020</b>	
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

## PERFORMING BRADENHEAD TEST

### General Procedure for Bradenhead Test

Identify: All valves prior to testing

Gauges: Install on each casing string to record pressure.

Assure: That all valves are in good working condition and closed at least 24 hours prior to testing.

Open: Each valve (Bradenhead, intermediate and casing valves) is to be opened separately.

Check Gauges: Record pressure on each gauge and casing string on BHT form. Open valves to atmosphere and record results on BHT form.

Designate what applies to the result of opening the valves for each string:

- |                        |           |
|------------------------|-----------|
| • Blow or Puff         | Yes or No |
| • Bled down to Nothing | Yes or No |
| • Steady Flow          | Yes or No |
| • Oil or Gas           | Yes or No |
| • Water                | Yes or No |

Start: Injection or SWD pump so tubing pressure can be read.

Instructions below apply to the District 1 Hobbs office since this must be reported on a form.

In case of pressure:

1. Record pressure reading on gauge.
2. Bleed and note time elapsed to bleed down.
3. Leave valve open for additional observation
4. Note any fluids expelled.

In absence of Pressure:

1. Leave valve open for additional observation.
2. Note types of fluids expelled.
3. Note if fluids persist throughout test.

Note. Tubing pressure on injection or SWD wells.

Test will be signed by person performing test with a contact phone number.

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 443828

CONDITIONS

Operator: SCOUT ENERGY MANAGEMENT LLC 13800 Montfort Road Dallas, TX 75240	OGRID: 330949
	Action Number: 443828
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
robert.asher	None	1/26/2026