

District I

1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Cross Timbers Energy LLC		API Number 30-025-23986	
Property Name North Wackarum Unit		Well No. 171	

* Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
N	14	17S	34E	660	S	1780	W	Lea

Well Status

TA'D WELL YES ☐ NO ☒	SHUT-IN YES ☐ NO ☒	INJECTOR ☒ SWD	PRODUCER OIL ☒ GAS	DATE 3-17-2025
--	--	--	--	--------------------------

OBSERVED DATA

	(A) Surface	(B) Interm(1)	(C) Interm(2)	(D) Prod Casing	(E) Tubing
Pressure	θ	θ	θ	θ	θ
Flow Characteristics					
Puff	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	CO2 ☐
Steady Flow	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	WTR ☒
Surges	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	GAS ☐
Down to nothing	☒ Y / N	☒ Y / N	Y / N	☒ Y / N	Type of Fluid
Gas or Oil	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Injected for
Water	Y / ☒ N	Y / ☒ N	Y / N	Y / ☒ N	Waterhead if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Post work over Repaired tbs/Packer leak.

Signature: Jake Baeza		OIL CONSERVATION DIVISION	
Printed name: Jake Baeza		Entered into RBDMS	
Title:		Re-test	
E-mail Address:			
Date: 3-17-25	Phone:		
	Witness:		

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 443591

CONDITIONS

Operator: CROSS TIMBERS ENERGY, LLC 400 West 7th Street Fort Worth, TX 76102	OGRID: 298299
	Action Number: 443591
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
robert.asher	None	1/26/2026