

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name		Property Name		API Number	
Morning STAR OPERATING LLC		Central VACUUM UNIT		30-025-25783	
				Well No. #016	

1. Surface Location

UL - Lot	Section	Township	Range	Feet from	N/S Line	Feet From	E/W Line	County
G	30	175	35E	2630	N	1330	E	LEA

Well Status

YES	TA'D WELL	NO	YES	SHUT-IN	NO	INJ	INJECTOR	SWD	OIL	PRODUCER	GAS	DATE
												1/12/2026

OBSERVED DATA

	(A)Surface	(B)Interim(1)	(C)Interim(2)	(D)Prod Csgng	(E)Tubing
Pressure	0			0	0
Flow Characteristics					
Puff	Y / 0	Y / N	Y / N	Y / 0	CO2
Steady Flow	Y / 0	Y / N	Y / N	Y / 0	WTR
Surges	Y / 0	Y / N	Y / N	Y / 0	GAS
Down to nothing	0 / N	Y / N	Y / N	0 / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BHT - DK

SPECIAL TEST REQUESTED (SPECT) - DK

CAL DATE: 1/12/2026 SN#15

Signature:	OIL CONSERVATION DIVISION		
Printed name:	Entered into RBDMS		
Title:	Re-test		
E-mail Address:			
Date:	Phone:		
		Witness: <i>Q. NMOC</i>	

NET ASTER

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 542609

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 542609
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
robert.trujillo	None	1/27/2026