

District 1
1635 N French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax (575) 393-0720

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING LLC		API Number 30-025-33335
Property Name CENTRAL VACUUM UNIT		Well No 168

1. Surface Location									
UL - Lot F	Section 36	Township 17S	Range 34E	Feet from 2068	NS Line FNL	Feet from 1467	EW Line FWL	County LEA	

Well Status											
YES	TA'D WELL ☒	YES	SHUT-IN ☒	INJ	INJECTOR	SWD	☒	OIL	PRODUCER	GAS	DATE 2/27/25

OBSERVED DATA

	(A) Surface	(B) Interf (1)	(C) Interf (2)	(D) Prod Casing	(E) Tubing
Pressure	0			250	320
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR
Surges	Y/N	Y/N	Y/N	Y/N	GAS
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of fluid Inferred for waterflood if applicable
Gas or Oil	Y/N	Y/N	Y/N	Y/N	
Water	Y/N	Y/N	Y/N	Y/N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature <i>Richard Paul</i>	OIL CONSERVATION DIVISION	
Printed name Richard Paul	Entered into RBDMS	
Title Case Operator	Re-test	
E-mail Address rpaul@ctfieldsvcs.com		
Date 2/27/25	Phone 817-739-5643	
	Witness	

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 445045

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 445045
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
robert.asher	None	1/27/2026