

District I
1025 N French Dr., Hobbs, NM 88240
Phone (575) 393-6161 Fax (575) 393-0020

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name MORNINGSTAR OPERATING LLC		API Number 30-025-33767	
Property Name WEST VACUUM UNIT		Well No 063	

1. Surface Location									
U/L - Lot G	Section 34	Township 17S	Range 34E		Feet from 2250	N/S Line FNL	Feet From 2250	E/W Line FEL	County LEA

Well Status									
TA'D WELL YES	☒ NO	YES	SHUT-IN ☒ NO	INJ	INJECTOR	SWD	☒ OIL	PRODUCER	GAS
									DATE 3-5-2025

OBSERVED DATA

	(A) Surface	(B) Interim (1)	(C) Interim (2)	(D) Prod Casing	(E) Tubing
Pressure	0	—	—	35#	35#
Flow Characteristics					
Puff	Y / ☒ N	Y / N	Y / N	Y / N	CO2 WTR GAS Type of Fluid Injected for Waterflood if applicable
Steady Flow	Y / ☒ N	Y / N	Y / N	Y / N	
Surges	Y / ☒ N	Y / N	Y / N	Y / N	
Down to nothing	☒ Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / ☒ N	Y / N	Y / N	Y / N	
Water	Y / ☒ N	Y / N	Y / N	Y / N	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature <i>John Stevenson</i>		OIL CONSERVATION DIVISION	
Printed name: JOHN STEVENSON		Entered into RBDMS	
Title: FOREMAN		Re-test	
E-mail Address:			
Date: 3-5-2025	Phone: 1-682-269-0257		
Witness			

INSTRUCTIONS ON BACK OF THIS FORM

Sante Fe Main Office
Phone: (505) 476-3441

General Information
Phone: (505) 629-6116

Online Phone Directory
<https://www.emnrd.nm.gov/oed/contact-us>

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 455861

CONDITIONS

Operator: MorningStar Operating LLC 400 W 7th St Fort Worth, TX 76102	OGRID: 330132
	Action Number: 455861
	Action Type: [UF-BHT] Bradenhead Test (BRADENHEAD TEST)

CONDITIONS

Created By	Condition	Condition Date
blydick	None	1/27/2026